



DCN No.
LAT-XR-06611-01

LAT PROJECT DOCUMENT CHANGE NOTICE (DCN)

SHEET 1 OF 1

| | | | |
|---|------------------------------------|----------------------------|---------------------|
| ORIGINATOR: Leonid Sapozhnikov | | PHONE: 650-926-2002 | DATE: 5/5/05 |
| CHANGE TITLE: DCN for TEM/TPS Performance Test Procedure | | | ORG.: |
| DOCUMENT NUMBER | TITLE | | NEW REV. |
| LAT-TD-04085 | TEM/TPS Performance Test Procedure | | 04 |
| | | | |
| | | | |
| | | | |
| | | | |

CHANGE DESCRIPTION (FROM/TO):
 Please see LAT-XR-06612-01 for changes to this document

REASON FOR CHANGE:


ACTION TAKEN: Change(s) included in new release DCN attached to document(s), changes to be included in next revision
 Other (specify):

| | |
|---|--------------------------|
| DISPOSITION OF HARDWARE (IDENTIFY SERIAL NUMBERS): | DCN DISTRIBUTION: |
| <input checked="" type="checkbox"/> No hardware affected (record change only) | |
| <input type="checkbox"/> List S/Ns which comply already: | |
| <input type="checkbox"/> List S/Ns to be reworked or scrapped: | |
| <input type="checkbox"/> List S/Ns to be built with this change: | |
| <input type="checkbox"/> List S/Ns to be retested per this change: | |
| <input type="checkbox"/> | |

SAFETY, COST, SCHEDULE, REQUIREMENTS IMPACT? YES NO
 If yes, CCB approval is required. Enter change request number:

| APPROVALS | DATE | OTHER APPROVALS (specify): | DATE |
|--|--------|---|--------|
| ORIGINATOR: L. Sapozhnikov (signature on file) | 5/5/05 | Thermal- J. Goodman (signature on file) | 5/6/05 |
| ORG. MANAGER: G. Haller (signature on file) | 5/5/05 | | |
| PSA- J. Cullinan (signature on file) | 5/5/05 | | |
| Manufacturing- R. Patterson (signature on file) | 5/5/05 | | |
| Elec.- D. Nelson (signature on file) | 5/9/05 | | |
| DCC RELEASE: Natalie Cramar (signature on file) | 5/9/05 | Doc. Control Level: <input checked="" type="checkbox"/> Subsystem <input type="checkbox"/> LAT IPO <input type="checkbox"/> GLAST Project | |

DCN No: LAT-XR-06611-01

| | | |
|---|---|-------------------------------|
|  | Document # LAT-TD-04085-04 | Date effective 05/04/2005 |
| | Author(s) L. Sapoznikov | Supersedes LAT-TD-04085-03 |
| | Subsystem/Office Electronics & DAQ Subsystem | |
| Document Title TEM/TPS Performance Test Procedure | | |

**Tower Electronics Module Assembly (TEM)/Tower Power Supply (TPS)
Performance Test Procedure**

TEM/TPS Performance Test Procedure

CHANGE HISTORY LOG

| Revision | Effective Date | Description of Changes |
|----------|----------------|--|
| 01 | 10/28/04 | Initial version |
| 02 | 01/06/05 | Added line 12 and 13 to Para. 5.5.1 and the data sheets to reflect the changes. Updated Figures 20, 36, 44, to indicate that the TPS is a Unit Under Test; Changed EGSE equipment: TEMPROD version to V01-00-02 under Software for the local PC |
| 03 | 02/14/05 | Changed LATTE version to P04-07-02 and TEMPROD version to V02-03-01. In Temperature Test, updated screenshot of window and added step to record ambient temperature. In Functional Test, updated screenshots to show Misc and Thorough buttons. Replaced Basic Test in CAL Noise and TKR Noise Tests, with Functional Test. Added steps to check indicator lights before demating during the CAL Noise and TKR Noise Tests. Removed references to gGTIC; these steps are now contained in the code. Added Mate/Demate Log. |
| 04 | 05/04/05 | Added Thermal Vac section in which all the tests are run in one test. |
| | | |

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

Table of Contents -TOC

1. SCOPE 6

2. DEFINITIONS AND ACRONYMS 7

 2.1 Definitions..... 7

 2.2 Acronyms..... 8

3. REFERENCES 9

 3.1 Applicable Documents..... 9

4. REQUIREMENTS..... 10

 4.1 General..... 10

 4.2 Test Personnel and Descriptions..... 10

 4.3 Test Readiness Review (TRR) and Post Test Review (PTR)..... 10

 4.4 Environmental Conditions 11

 4.5 Contamination Control..... 11

 4.6 Handling and Transportation 11

 4.7 ESD..... 11

 4.8 Mate/Demate Connectors..... 12

 4.9 Test Equipment 12

 4.10 Test Data and Review 12

 4.11 Flight Hardware Log Book 12

 4.12 Nonconforming Test Data, Equipment and Software..... 12

 4.13 Redlines to Documents 12

 4.14 Crane Operations 13

 4.15 Quality Assurance..... 13

 4.15.1 Product Assurance Requirements 14

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

TEM/TPS Performance Test Procedure

4.16 Warnings, Cautions, and Notes..... 14

4.17 Safety 14

5. PROCEDURE..... 15

5.1 Test Procedure Instructions/Information 15

5.1.1 Test Prerequisites 15

5.1.2 Test Sequence 15

5.1.3 Test Equipment 15

5.1.4 Participant List 17

5.1.5 Unit Under Test (UUT)..... 18

5.2 Pre-Operation Verifications 19

5.3 Test Descriptions 20

5.4 Calibration Tests 21

5.4.1 CAL Calibration High Voltage Test Procedure..... 21

5.4.2 TRK Calibration High Voltage Test Procedure..... 29

5.4.3 TPS Calibration Tower Current Test Procedure..... 38

5.5 Main Tests..... 44

5.5.1 Main Tests Setup Procedure 44

5.5.2 Monitor Margin and Bias Test Procedure..... 47

5.5.3 Temperature Monitor Test Procedure..... 50

5.5.4 Basic Test Procedure..... 53

5.5.5 Front End Test Procedure 55

5.5.6 TEM FIFO Test Procedure 57

5.6 Functional Test Procedure 59

5.7 Noise Tests..... 62

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

TEM/TPS Performance Test Procedure

5.7.1 Noise Test Prerequisite 62

5.7.2 CAL Noise Test Procedure 62

5.7.3 TKR Noise Test Procedure 71

5.8 Thermal Vac Test..... 81

5.8.1 Thermal Vac Test Setup Procedure 81

5.8.2 Thermal Vac Test Procedure 88

Appendix A (Data Sheets and Covers) 91

Appendix B Connector Mate/Demate Log 107

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

1. SCOPE

This document provides the process for setup and instructions for testing the Tower Electronics Module (TEM)/Tower Power Supply (TPS) and the Electrical Ground Support Equipment (EGSE) TEM Test Stand.

Note: This document shall be considered subordinate to any Assembly and Inspection Data Sheet (AIDS) that is used in conjunction with this testing process.

2. **DEFINITIONS AND ACRONYMS**

The following terms, abbreviations, and acronyms are used in this document:

2.1 **Definitions**

| | |
|----------|------------------------------------|
| A, An | Analog |
| D, Dg | Digital |
| F | Functional |
| Hz | Hertz, unit of frequency |
| MHz | Megahertz |
| mV | millivolt, 10^{-3} Volt |
| Ω | ohm, unit of electrical resistance |
| s, sec | seconds |
| μ | 10^{-6} |
| V | Volt |
| W | Watt |

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

2.2 Acronyms

| | |
|-------|---|
| AIDS | Assembly and Inspection Data Sheet |
| BOB | Break-Out-Box |
| CAL | Calorimeter |
| CPT | Comprehensive Performance Test |
| EGSE | Electrical Ground Support Equipment |
| ETech | Electrical Technician Electrical Ground Support Equipment |
| GASU | Global trigger Anti-collision Spacecraft Unit |
| LPT | Limited Performance Test |
| MTech | Mechanical Technician |
| PTR | Post Test Review |
| QAE | Quality Assurance Engineer |
| TC | Test Conductor |
| TD | Test Director |
| TEM | Tower Electronics Module |
| TKR | Tracker |
| TPS | Tower Power Supply |
| TRR | Test Readiness Review |
| UUT | Unit Under Test |

3. REFERENCES

The list below provides documents that are to be used as references for this procedure:

3.1 **Applicable Documents**

| <u>Document Number</u> | <u>Description</u> |
|------------------------|---|
| <u>SPECIFICATIONS</u> | |
| LAT-TD-00778 | LAT Environmental Specification |
| <u>PROCEDURES</u> | |
| <u>PLANS</u> | |
| LAT-MD-00039 | Performance Assurance Implementation Plan |
| LAT-MD-00078 | GLAST LAT System Safety Program Plan |
| LAT-MD-00404 | LAT Contamination Control Plan |
| LAT-MD-00408 | LAT Program Instrument Performance Verification Plan |
| LAT-SS-00296 | T & DF Test Plan |
| LAT-TD-00297 | LAT Electronics Test Plan |
| <u>DRAWINGS</u> | |
| <u>OTHER</u> | |
| LAT-MD-00091 | GLAST Quality Manual |
| LAT-MD-00471 | Control of Nonconforming Product |
| LAT-MD-00472 | Corrective and Preventative Action |
| LAT-MD-00473 | Handling, Storage, Packing, Preservation and Delivery |

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

4. REQUIREMENTS

This section lists the requirements that shall be followed during the TEM Qualification and Acceptance process.

4.1 General

The Performance Assurance Implementation Plan, LAT-MD-00039 shall be utilized to ensure that the products produced by the GLAST LAT project intended for design qualification, flight and critical ground support equipment usage meet the required levels of quality and functionality for their intended purposes.

This document shall follow the LAT Program Instrument Performance Verification Plan LAT-MD-00408 which details the LAT and its subsystem verification test flow.

The LAT T & DF Test Plan, LAT-TD-00296 shall be utilized to address the overall requirements at engineering model, qualification and production level phases. This document defines the time period from post circuit board fabrication until electronic box delivery to LAT Integration and Test.

Testing within this document shall conform to the requirements stated in LAT Performance and Operations Test Plan LAT-MD-02730 for all testing that relates to LAT I & T.

4.2 Test Personnel and Descriptions

Test personnel are described in GLAST LAT Integration and Test Subsystem Test Plan, LAT-MD-01376.

4.3 Test Readiness Review (TRR) and Post Test Review (PTR)

The TRR and PTR are organizational meetings that shall be held at the appropriate times to inform all parties about the testing that is to be accomplished and has been completed. The TRR and PTR meetings are defined in the GLAST LAT Integration and Test Subsystem Test Plan, LAT-MD-01376.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

4.4 Environmental Conditions

Testing performed in accordance with this document shall conform to standard environmental test conditions unless specific test requirements within this document exist. Standard Environmental test conditions are as follows:

- Dynamic Mechanical Conditions: No load, at rest
- Temperature: 18.3 to 25.7°C
- Atmospheric Pressure: Uncontrolled local conditions
- Humidity: 30% to 50% RH for testing when the Calorimeter or Engineering Model (EM) Calorimeters are present. For all other testing 30% to 60% RH is required.

This document shall follow the LAT Environmental Specification, LAT-SS-00778 for all testing where non standard environments are required. The Environmental Specification defines the thermal, vibration and on-orbit exposure design and test environments for the LAT instrument and its subsystems.

4.5 Contamination Control

The Contamination Control Plan defines the overall contamination control requirements necessary to establish hardware cleanliness for the GLAST LAT program. When work is performed at SLAC follow LAT-MD-01386. When work is performed elsewhere follow LAT-MD-00404.

4.6 Handling and Transportation

This document shall follow the requirements found in the Handling, Storage, Package, Preservation and Delivery document, LAT-MD-00473. This document establishes handling, storage, packaging and transportation practices adequate to maintain the safety, reliability and quality of SLAC LAT flight hardware items and achieve their damage free delivery to the place and time of ultimate use.

4.7 ESD

The CAL, TKR, T & DF Contamination Control Plan and the LAT Contamination Control Plan define the ESD requirements for the GLAST LAT program. When work is performed at SLAC follow LAT-MD-01386. When work is performed elsewhere follow LAT-MD-00404

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

4.8 Mate/Demate Connectors

This document shall follow the requirements found in the Mate and Demate Workmanship Standard LAT-PS-04459. The mate/demate process shall be followed for each and every connector mate. This consists of a visual inspection of the interface, cleaning if required, and proper mating techniques.

4.9 Test Equipment

This document shall follow the requirements found in the LAT Program Instrument Performance Verification Plan, LAT-MD-00408, which defines calibration, accuracy, substitutions, etc. for the test equipment.

4.10 Test Data and Review

This document shall follow the requirements found in the LAT Program Instrument Performance Verification Plan, LAT-MD-00408, which defines the test data sheets and details the personnel that reviews test data. Test data shall be recorded on the data sheets that are found in Appendix A of this document. The data sheets and any supporting data shall use a cover sheet that is found in Appendix A of this document.

4.11 Flight Hardware Log Book

The LAT Program Instrument Performance Verification Plan, LAT-MD-00408 requires that a log of hardware installation, software installation, power ON and mates/demates to flight connectors shall be kept for each flight unit. The log book is part of the package that is deliverable to the customer.

4.12 Nonconforming Test Data, Equipment and Software

This document shall follow the requirements found in the Control of Nonconforming Product, LAT-MD-00471. This document establishes methods to identify and control nonconforming product developed by the LAT project team.

4.13 Redlines to Documents

The users of this document shall follow the requirements found in the Redline/Blackline Engineering Documents, LAT-MD-03474.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

4.14 Crane Operations

Before a crane (or any lifting device) is used it should be verified that the proof loading is current and the expected load to be lifted does not exceed the load capacity of the device. The operator shall have a current certification for the operation.

There shall be three people present before, during and at the completion of all lifting operations. Each one of these people shall perform only one of the following three duties:

- Crane Operator – When the crane operator controls the crane no other duties shall be performed. At other times this person may help with the mechanical or electrical duties.
- Spotter – During the lifting operation this person guides the item that is to be moved up or down, checks clearances and the overall movement of all items. At other times this person may help with the mechanical or electrical duties.
- Safety Person (for crane operations only) – Before lifting the item, this person double checks all operations and the removal of bolts/hardware from the item to be moved. During crane operations this person is an observer of the operation and directs the overall lifting operation.

4.15 Quality Assurance

This document shall follow the requirements found in the Corrective and Preventative Action document, LAT-MD-00472 and the GLAST Quality Manual, LAT-MD-00091 and LAT Program Instrument Performance Verification Plan, LAT-MD-00408.

The Corrective and Preventative Action document establishes the method to be used to initiate, implement, evaluate and record corrective and preventive actions. The GLAST Quality Manual defines the methods implemented by the GLAST LAT project to ensure consistent quality of all processes for procurement, design, development and production of flight hardware, flight software, calibration and all associated ground support equipment interfacing with flight hardware and software. The LAT Program Instrument Performance Verification Plan defines test configuration, data sheets and review of test results.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

4.15.1 Product Assurance Requirements

The Quality Assurance Engineer (QAE) shall witness the initial test setup and validation operations. In the event of a failure a Non Conformance Report (NCR) shall be written. The root cause and corrective action shall be identified and there shall be QAE approval before the operation is continued. Any deviation from this document requires approval from the QAE as well as the Test Conductor (TC).

4.16 Warnings, Cautions, and Notes

The following SAFETY ALERTS are intended to create awareness of the potential safety hazards and the steps that must be taken to avoid accidents. These same alerts are used throughout this document to identify specific hazards that may endanger personnel and/or equipment.

Identification of every conceivable hazardous situation is impossible. Therefore, all personnel have the responsibility to diligently exercise safe practices whenever exposed to this equipment.

WARNING: Indicates a potential hazardous situation which, if not avoided, could result in death or injury.

CAUTION: Indicates a potential hazardous situation which, if not avoided, could result in damage to equipment.

Note: Indicates a notification of information that is important, but not hazard related.

4.17 Safety

This document shall follow the requirements found in the GLAST LAT System Safety Program Plan, LAT-MD-00078. This document defines all phases of the LAT program including: design, development, fabrication, handling, transportation, storage, test, assembly and operation.

WARNING: When high voltages are present extreme care should be exercised.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5. PROCEDURE

This procedure is used for Performance Testing of the circuits of the TEM.

Unless otherwise noted use a DVM for all measurements.

Note: When performing measurements with a DMM connect the negative lead first.

5.1 Test Procedure Instructions/Information

This section provides the general instructions and information that are used and required to perform this procedure, including: test parameters, sequence, equipment and test participants.

5.1.1 Test Prerequisites

This section describes processes and procedures that must be completed prior to performing the tests in this document.

Before this test is run, the following tests must be completed:

- TEM Performance Test Procedure: LAT-TD-03415
- TPS Performance Test Procedure: LAT-TD-01652

5.1.2 Test Sequence

This section describes the requirements of the event sequence for performing this procedure. Tests are to be performed in the order listed in this document unless otherwise specified. It is permissible for Assembly Instruction Data Sheets (AIDS) to be used to change the order of tests or select a single test paragraph to be performed. In that case, the data sheet for the test performed will be included in the end item data package linked to the AIDS step that required it. Test sequencing can also be changed in a TRR and black lined into the test procedure.

5.1.3 Test Equipment

The test equipment listed below is necessary for the tests described in this procedure. If additional equipment is used, add it to the table below with the signature of the TC and QAE, proceed with the test.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

TEM/TPS Performance Test Procedure

5.1.3.1 EGSE

To record the test equipment, cables, connector savers and software:

1. Record the information for all equipment on the data sheet. See the list below for descriptions of the information to be recorded.
 - Description and Manufacturer
 - Model/LAT number
 - Serial/Revision number
 - Calibration due date (enter NA for non calibrated equipment)
 - Validation completion date for all EGSE

The list below indicates the equipment that is used to perform this procedure:

| Test Equipment Description, Manufacturer | Model/LAT Number |
|--|---|
| VME Crate, Dawn VME Products | 11-1011777-2119 |
| VME, TST-STP Trans card | LAT-DS-00999 |
| VME SBC MVME2304 card, Motorola | PN MVME2304-0123 |
| VME LCB Mezzanine card | LAT-TD-00860 |
| Software for the local PC | LATTE P04-07-02 Downloaded from www-glast.slac.stanford.edu/IntegrationTest/ONLINE/updates/ |
| Software for the local PC | TEMPROD V02-03-01 Found in /nfs/slac/g/glast/online/cvsroot/temprod See TEMPROD/History for more information. |
| DC Power supply #1, BK Precision | BK 1697 |
| DC Power supply #2, BK Precision | BK 1697 |
| 28 Volt supply cable | LAT-DS-03246 |
| PS Control cable | LAT-DS-04831 |
| TEM to GASU cable | LAT-DS-02106 |
| LCB Transition board cable | LAT-DS-03247 |
| TEM Test Board Assembly | LAT-DS-04465 |
| TEM Test board cooling fan assembly | LAT-DS-03567 |
| CAT5 Ethernet cable | TRD855PL-50 |

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

TEM/TPS Performance Test Procedure

| Test Equipment Description, Manufacturer | Model/LAT Number |
|--|-------------------------------|
| RS-232 Cable | TDC003-7 (RECO98M connectors) |
| Ground jumper, Banana, Pomona | B-12-0 |
| PS extension cable | LAT-DS-04629 |
| Digital Multimeter, Fluke/Meterman | 87-III/38XR |
| Connector Savers (28 pin), L Com | DGBH28MF |
| Connector Savers (51 pin), Glenair | MWDM2L-51USP1 |
| Connector Savers (69 pin), SLAC | LAT-DS-04724 |
| Connector Savers (78 pin), L Com | DGBH78MF |
| Breakout Box Assembly (BOB) (78 pin), SLAC | LAT-DS-03580 |
| Breakout Cable (BOC), SLAC | LAT-DS-04273 |
| Breakout Cable (BOC), SLAC | LAT-DS-04275 |
| Load | LAT-DS-04822 |
| Load | LAT-DS-04823 |
| 1 MHz Filter | LAT-DS-04767 |
| Noise Measurement Adapter, 51-Pin, SLAC | LAT-DS-04821 |
| Noise Measurement Adapter, 69-Pin, SLAC | LAT-DS-04820 |
| True RMS Volt Meter, Agilent (HP) | 3400A |
| Delay Line, Lemo To Bnc 4N, from SLAC Stores | STORES ID #078697 |
| | |

5.1.3.2 User Interfaces

This test uses GUIs that are based on the Run Control software that has been provided for GLAST by SLAC. Each of the GUIs is described when they are first used in the body of the test procedure.

5.1.4 Participant List

This section provides a data sheet to record test participants.

1. Record all test participants in the data sheet.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.1.5 Unit Under Test (UUT)

The units under test are the TEM and TPS. The serial number for these units is the 4-digit part of the GLAT number, which is located on the bar code sticker on the unit. Record these numbers on the data sheet cover page and table headings, and enter them in the test application window when requested.

5.2 Pre-Operation Verifications

This section details the pre-operation verification checks before testing the UUT.

To perform the pre-operation verification checks:

CAUTION: Follow ESD processes during this checkout.

Note: Prior to the connection of any hardware to other electronics, verify that all power supplies, signal generators, VME racks, and any other test and measurement equipment are connected to the same AC ground. The simplest way to do this is to connect all AC-powered equipment to the same power strip. In cases where this is not practical (e.g., possibly a thermal-vacuum test), greater care must be taken to ensure there are no floating grounds since this would represent a hazard to the electronics.

Note: Leave all connector savers in place until the actual flight mate is to be made. The AIDS provides authorization to install and remove connector savers.

Note: All flight mates and demates must be completed and entered into the mate demate log before measurements are made or testing can start.

1. Notify QAE that testing is expected to start, so the QAE can arrange to be present for the setup and start of testing. Record per the data sheet.
2. Verify that the Test Readiness Review has concluded and all parties have signed the cover sheet. Record per the data sheet.
3. Record the serial numbers and locations per the data sheet. The serial number for the TEM and for the TPS is the 4-digit part of the GLAT number, which is located on the bar code sticker on the unit.
4. Turn off the LAT or EGSE power. Record in the data sheet.
5. Verify connector savers are on all flight hardware (install the connector savers per authorization from an AIDS if necessary). Record in the data sheet.
6. Verify that the test equipment and participant lists have been completed.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.3 Test Descriptions

The tests that are run as part of this document are:

- Calibration Tests:
 - Calorimeter (CAL) – Calibrates the TEM measurement of the CAL HV current against an external measurement and logs the internal current measurement as a function of voltage.
 - Tracker (TKR) – Calibrates the TEM measurement of the TKR HV current against an external measurement and logs the internal current measurement as a function of voltage.
 - TEM/TPS – Calibrates the TEM measurement of the tower current against the power supply measurement.
- Main Tests
 - Test Setup for Main Tests – Opens Run Control. This is not a test of the TEM.
 - Monitor Margin and Bias Midrange – Sets the margin and bias voltages to the nominal (mid) range level and then checks the output reading.
 - Temperature Monitor – Checks the temperature readings.
 - Basic – Checks the basic TEM functions (none of the front end connections).
 - Front End – Checks the front end connections and the front end communication.
 - TEM FIFO – Tests the FIFOs on the TEM
- Functional Tests – Tests all the functional registers on the TEM individually.
- Noise Tests – Checks the noise requirements for CAL and TKR power.
 - CAL Noise Test
 - TKR Noise Test

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.4 Calibration Tests

5.4.1 CAL Calibration High Voltage Test Procedure

This section provides instructions to test the calibration of the CAL.

To setup and run the calibration test:

1. Verify that the power is off to power supply #1 and the VME Crate.
2. Connect all the equipment and cables per the interconnect drawing in the figure below.




Figure 1. CAL Calibration Test setup Interconnection Diagram

3. Set the DMM to the auto-ranging setting. Record in the data sheet.
4. Measure DMM lead resistance by connecting the two leads together. Record in the data sheet.
5. Connect the BOB chassis to technical ground. Measure the resistance between the BOB chassis and technical ground. Record in the data sheet.
6. Ensure all shorting plugs are removed from the BOB. Record in the data sheet.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.4.1 CAL Calibration High Voltage Test Procedure (continued)

7. Measure the resistance between the Unit Under Test (UUT) chassis and technical ground. Record in the data sheet.
8. Measure the resistance between the test equipment chassis and technical ground. Record in the data sheet.
9. Setup the BOB and configure the DMM per the figure below following this process:
 - a) Connect P2 of the BOC (LAT-DS-04275) to J2 on the BOB (LAT-DS-03580).
 - b) Connect P1 of the BOC to JC-0 on the TEM.
 - c) Connect the load (LAT-DS-04822) to the black lead of the DMM and insert it into the red terminal of test point 69 on the BOB.
 - d) Insert the red lead of the DMM into the red terminal of test point 68.




Figure 2. CAL Calibration Test DMM Setup

- e) Configure the DMM and test leads in current-measuring mode in the mA range.
- f) Record on the data sheet.
10. Set the function generator to 20 MHz square wave.
11. Turn on power supply #1 and apply 28.0 volts.
12. Open the “ttermpro” file located in the C:\Program Files\TeraTermProSSH\ directory and connect to the VME Crate using the serial port (COM3).

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.4.1 CAL Calibration High Voltage Test Procedure (continued)

13. Apply power to the VME Crate.
14. Wait for the boot to finish.
15. Open a Command Prompt window.
16. Change the directory to V:\GLAST\Electronics\Teststands\gitot.
17. Type in “runcontrol.bat” and enter.

5.4.1 CAL Calibration High Voltage Test Procedure (continued)

18. The “Run Control Main” window appears as shown below.




Figure 3. Run Control Main Window

Note: Do not change the options in this window.

19. At the “Run Control Main” window, click on the “Select Application” button. The “Select an application” window appears as shown below.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.4.1 CAL Calibration High Voltage Test Procedure (continued)

20. Select the directory
V:/GLAST/Electronics/TEMPROD/CalibHVTTest/




Figure 4. Select an Application Window

21. Select “calibTest.py”.
22. Click on the “Open” button to open the file.
23. At the “Run Control Main” window, click on the ► button.

5.4.1 CAL Calibration High Voltage Test Procedure (continued)

24. The “Calibration High Voltage Test Window” appears as shown below. The indicators following the ranges are clear before the test.




Figure 5. Calibration High Voltage Test Window—CAL Test

25. Select the Calorimeter box and clear the Tracker and TPS Calibration boxes.
26. Enter the TPS serial number in the window. The TPS serial number is the number on the bar code sticker on the TPS.
27. Enter the TEM serial number in the window. The TEM serial number is the number on the bar code sticker on the TEM.

5.4.1 CAL Calibration High Voltage Test Procedure (continued)

28. Click on the “Start” button. The “Current Value Window” appears.




Figure 6. Current Value Window

29. Enter the DMM reading in the “Current Value Window” and click OK.
30. Repeat steps 28 and 29 two more times. (The “Current Value Window” appears three times in all.) If there are any errors, they will appear in the Messages box and in the log file.

Note: This test takes about a minute or less to run.

31. Verify that the indicator is green, indicating good data (a red light indicates failure of the test) and that no errors appear in the Messages box. **Record** verifications per the data sheet.
32. Open and print the log file (see the sample of the log file below) and attach it to the data cover sheet.

5.4.1 CAL Calibration High Voltage Test Procedure (continued)

```

cal_20041011_113533 - Notepad
File Edit Format View Help
11:35:33 calibrating cal
11:36:07 bias voltage,dvm current,read current
11:36:07 50.6233211233,0.6,0.53197347315
11:36:11 98.9652014652,1.2,1.14857908976
11:36:15 75.2258852259,0.8,0.858411740765
11:36:15 slope in mA(dvm)/mA(tem),intercept in mA(dmv)
11:36:15 0.96559565634,0.0494623655914
11:36:15 tem current (mA),dvm extapolated current,bias voltage (v)
11:36:15 0.858411740765,0.878341013825,75.2258852259
11:36:16 4.49759390936,4.39231950845,2.83638583639
11:36:17 4.49759390936,4.39231950845,2.83638583639
11:36:17 3.94143982379,3.85529953917,5.73443223443
11:36:18 3.94143982379,3.85529953917,5.73443223443
11:36:18 3.31274390098,3.24823348694,8.81746031746
11:36:19 3.31274390098,3.24823348694,8.81746031746
11:36:20 2.732409203,2.68786482335,11.9004884005
11:36:20 2.732409203,2.68786482335,11.9004884005
11:36:21 2.15207450502,2.12749615975,14.9218559219
11:36:22 2.15207450502,2.12749615975,14.9218559219
11:36:22 1.54755919462,1.54377880184,18.0048840049
11:36:23 1.54755919462,1.54377880184,18.0048840049
11:36:24 0.95134190428,0.971735791091,21.0879120879
11:36:24 0.95134190428,0.971735791091,21.0879120879
11:36:25 0.374799492447,0.411367127496,24.1709401709
11:36:26 0.374799492447,0.411367127496,24.1709401709
11:36:26 0.290167348991,0.329646697389,24.7258852259
11:36:27 0.290167348991,0.329646697389,24.7258852259
11:36:28 0.265986736575,0.306298003072,24.7258852259
11:36:28 0.265986736575,0.306298003072,24.7258852259
11:36:29 0.278077042783,0.31797235023,24.7258852259
11:36:30 0.278077042783,0.31797235023,24.7258852259
11:36:30 0.290167348991,0.329646697389,24.7258852259
11:36:31 0.290167348991,0.329646697389,24.7258852259
11:36:32 0.278077042783,0.31797235023,24.9108669109
11:36:32 0.278077042783,0.31797235023,24.9108669109
11:36:33 0.302257655199,0.341321044547,27.0073260073
11:36:34 0.302257655199,0.341321044547,27.0073260073
11:36:34 0.314347961407,0.352995391705,28.9188034188
11:36:35 0.314347961407,0.352995391705,28.9188034188
11:36:36 0.338528573823,0.376344086022,30.8919413919
11:36:36 0.338528573823,0.376344086022,30.8919413919
11:36:37 0.362709186239,0.399692780338,32.8034188034
11:36:38 0.362709186239,0.399692780338,32.8034188034
11:36:38 0.386889798655,0.423041474654,34.7765567766
11:36:39 0.386889798655,0.423041474654,34.7765567766
11:36:40 0.435251023486,0.469738863287,36.688034188
11:36:41 0.435251023486,0.469738863287,36.688034188
11:36:41 0.435251023486,0.469738863287,38.6611721612
11:36:42 0.435251023486,0.469738863287,38.6611721612
11:36:43 0.47152194211,0.504761904762,40.5726495726
    
```

Figure 7. Sample Log File

Note: The test log files are saved as C:/TEMPROD/log/CalibHVTest/cal_date_time.log.
One file is created by running this test.

33. Click on the “Close” button to close the test environment.
34. Turn off power supply #1.
35. Turn off power to the VME Crate.
36. Demate the BOB from the TEM.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.4.2 TRK Calibration High Voltage Test Procedure

This section provides instructions to test the calibration of the TKR.

WARNING: The TEM/TPS internally produces over 50 V at up to 10 mA. Do not manipulate the TEM/TPS during the test procedure. Do not disassemble until the power supplies have been turned off.

To setup and run the calibration test:

1. Verify that the power is off to power supply #1 and the VME Crate.
2. Connect all the equipment and cables per the interconnect drawing in the figure below.




Figure 8. TKR Calibration Test setup Interconnection Diagram

3. Set the DMM to the auto-ranging setting. Record in the data sheet.
4. Measure DMM lead resistance by connecting the two leads together. Record in the data sheet.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.4.2 TRK Calibration High Voltage Test Procedure (continued)

5. Connect the BOB chassis to technical ground. Measure the resistance between the BOB chassis and technical ground. Record in the data sheet.
6. Ensure all shorting plugs are removed from the BOB. Record in the data sheet.
7. Measure the resistance between the Unit Under Test (UUT) chassis and technical ground. Record in the data sheet.
8. Measure the resistance between the test equipment chassis and technical ground. Record in the data sheet.
9. Setup the BOB and configure the DMM per the figure below following this process:
 - a) Connect P2 of the BOC (LAT-DS-04273) to J2 on the BOB (LAT-DS-03580).
 - b) Connect P1 of the BOC to JT-0 on the TEM.
 - c) Connect the load (LAT-DS-04823) to the black lead of the DMM and insert it into the red terminal of test point 40 on the BOB.
 - d) Insert the red lead of the DMM into the red terminal of test point 37.




Figure 9. TRK Calibration Test DMM Setup

- e) Configure the DMM and test leads in current-measuring mode in the mA range.
 - f) Record in the data sheet.
10. Set the function generator to 20 MHz square wave.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.4.2 TRK Calibration High Voltage Test Procedure (continued)

11. Turn on power supply #1 and apply 28.0 volts.
12. Open the “ttermpro” file located in the C:\Program Files\TeraTermProSSH\ directory and connect to the VME Crate using the serial port (COM3).
13. Apply power to the VME Crate.
14. Wait for the boot to finish.
15. Open a Command Prompt window.
16. Change the directory to V:\GLAST\Electronics\Teststands\gitot.
17. Type in “runcontrol.bat” and enter.

5.4.2 TRK Calibration High Voltage Test Procedure (continued)

18. The “Run Control Main” window appears as shown below.




Figure 10. Run Control Main Window

Note: Do not change the options in this window.

19. At the “Run Control Main” window, click on the “Select Application” button. The “Select an application” window appears as shown below.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.4.2 TRK Calibration High Voltage Test Procedure (continued)

20. Select the directory
V:/GLAST/Electronics/TEMPROD/CalibHVTTest/




Figure 11. Select an Application Window

21. Select “calibTest.py”.
22. Click on the “Open” button to open the file.
23. At the “Run Control Main” window, click on the ► button.

5.4.2 TRK Calibration High Voltage Test Procedure (continued)

24. The “Calibration High Voltage Tests Window” appears as shown below. The indicators following the ranges are clear before the test.




Figure 12. Calibration High Voltage Test Window—TRK Test

25. Select the Tracker box and clear the Calorimeter and TPS Calibration boxes.
26. Enter the TPS serial number in the window. The TPS serial number is the number on the bar code sticker on the TPS.
27. Enter the TEM serial number in the window. The TEM serial number is the number on the bar code sticker on the TEM.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.4.2 TRK Calibration High Voltage Test Procedure (continued)

28. Click on the “Start” button. The “Current Value Window” appears.




Figure 13. Current Value Window

29. Enter the DMM reading in the “Current Value Window” and click OK.
30. Repeat steps 28 and 29 two more times. (The “Current Value Window” appears three times in all.) If there are any errors, they will appear in the Messages box and in the log file.
- Note: This test takes about a minute or less to run.
31. Verify that the indicator is green, indicating good data (a red light indicates failure of the test) and that no errors appear in the Messages box. **Record** verifications per the data sheet.

5.4.2 TRK Calibration High Voltage Test Procedure (continued)

32. Open and print the log file (see the sample of the log file below) and attach it to the data cover sheet.




Figure 14. Sample Log File

Note: The test log files are saved as C:/TEMPROD/log/CalibHVTTest/tkr_date_time.log.
One file is created by running this test.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.4.2 TRK Calibration High Voltage Test Procedure (continued)

33. Click on the “Close” button to close the test environment.
34. Turn off power supply #1.
35. Turn off power to the VME Crate.
36. Demate the BOB from the TEM.

5.4.3 TPS Calibration Tower Current Test Procedure

This section provides instructions to test the calibration of the TPS.

To setup and run the calibration test:

1. Verify that the power is off to power supply #1 and the VME Crate.
2. Disconnect the Test Board Cooling Fan Assembly by demating the cable (LAT-DS-03567) from Power Supply #1. Record in the data sheet.
3. Connect all the equipment and cables per the interconnect drawing in the figure below.




Figure 15. TPS Calibration Test setup Interconnection Diagram

4. Set the DMM to the auto-ranging setting. Record in the data sheet.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.4.3 TPS Calibration Tower Current Test Procedure (continued)

5. Measure DMM lead resistance by connecting the two leads together. Record in the data sheet.
6. Measure the resistance between the Unit Under Test (UUT) chassis and technical ground. Record in the data sheet.
7. Measure the resistance between the test equipment chassis and technical ground. Record in the data sheet.
8. Set the function generator to 20 MHz square wave.
9. Turn on power supply #1 and apply 28.0 volts.
10. Open the “ttermpro” file located in the C:\Program Files\TeraTermProSSH\ directory and connect to the VME Crate using the serial port (COM3).
11. Apply power to the VME Crate.
12. Wait for the boot to finish.
13. Open a Command Prompt window.
14. Change the directory to V:\GLAST\Electronics\Teststands\gitot.
15. Type in “runcontrol.bat” and enter.

5.4.3 TPS Calibration Tower Current Test Procedure (continued)

16. The “Run Control Main” window appears as shown below.




Figure 16. Run Control Main Window

Note: Do not change the options in this window.

17. At the “Run Control Main” window, click on the “Select Application” button. The “Select an application” window appears as shown below.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.4.3 TPS Calibration Tower Current Test Procedure (continued)

18. Select the directory
V:/GLAST/Electronics/TEMPROD/CalibHVTest/




Figure 17. Select an Application Window

19. Select “calibTest.py”.
20. Click on the “Open” button to open the file.
21. At the “Run Control Main” window, click on the ► button.

5.4.3 TPS Calibration Tower Current Test Procedure (continued)

22. The “Calibration High Voltage Tests Window” appears as shown below. The indicators following the ranges are clear before the test.




Figure 18. Calibration High Voltage Test Window—TPS Test


23. Select the TPS Calibration box and clear the Calorimeter and Tracker boxes.
24. Ensure that the Serial Port is correct. If not, enter the correct port in the “Calibration High Voltage Test Window.”
25. Enter the TPS serial number in the window. The TPS serial number is the number on the bar code sticker on the TPS.
26. Enter the TEM serial number in the window. The TEM serial number is the number on the bar code sticker on the TEM.
27. Click on the “Start” button. If there are any errors, they will appear in the Messages box and in the log file.

Note: This test takes about 40 seconds to run.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.4.3 TPS Calibration Tower Current Test Procedure (continued)

28. Verify that the indicator is green, indicating good data (a red light indicates failure of the test) and that no errors appear in the Messages box. **Record** verifications per the data sheet.
29. Open and print the log file (see the sample of the log file below) and attach it to the data cover sheet.



```
tps_666_20041021_111849 - Notepad
File Edit Format View Help
11:18:50 TPS calibration data for TPS 666
11:18:53 dv 0.007937: current 0.190000
11:18:55 dv 0.013431: current 0.530000
11:18:58 dv 0.017094: current 0.740000
11:19:01 dv 0.021978: current 1.090000
11:19:01 slope, intercept
11:19:01 63.593793, -0.323395
```

Figure 19. Sample Log File

Note: The test log files are saved as C:/TEMPROD/log/CalibHVTtest/tps_ID_date_time.log.
One file is created by running this test.

30. Click on the “Close” button to close the test environment.
31. Turn off power supply #1.
32. Turn off power to the VME Crate.
33. Reconnect the Test Board Cooling Fan Assembly by connecting the cable (LAT-DS-03567) to Power Supply #1.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.5 Main Tests

5.5.1 Main Tests Setup Procedure

This section provides instructions to setup the TEM/TPS for the Main Tests.

To setup the TEM/TPS Main Tests:

34. Verify that the power is off to power supply #1 and the VME Crate.
35. Connect all the equipment and cables per the interconnect drawing in the figure below.




Figure 20. Monitor Margin and Bias Test setup Interconnection Diagram

36. Set the DMM to the auto-ranging setting. Record in the data sheet.
37. Measure DMM lead resistance by connecting the two leads together. Record in the data sheet.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.5.1 Main Tests Setup Procedure (continued)

38. Measure the resistance between the UUT chassis and technical ground. Record in the data sheet.
39. Measure the resistance between the test equipment chassis and technical ground. Record in the data sheet.
40. Set the function generator to 20 MHz square wave.
41. Turn on power supply #1 and apply 28.0 volts.
42. Open the “ttermpro” file located in the C:\Program Files\TeraTermProSSH\ directory and connect to the crate using the serial port (COM3).
43. Apply power to the VME Crate.
44. Wait for the boot to finish.
45. Disconnect the fan. Record the current draw at external power supply #1 in the data sheet and verify that it is within the specified range.
46. Reconnect the fan.
47. After the boot-up process for the VME has completed turn on power supply #2 and apply 3.3 volts.
48. Open a Command Prompt window.
49. Change the directory to V:\GLAST\Electronics\Teststands\gitot.
50. Type in “runcontrol.bat” and enter.

5.5.1 Main Tests Setup Procedure (continued)

51. The “Run Control Main” window appears as shown below.




Figure 21. Run Control Main Window

Note: Do not change the options in this window.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.5.2 Monitor Margin and Bias Test Procedure

This section provides instructions to test the TEM/TPS environmental monitor.

To run the TEM/TPS environmental monitor test:

1. At the “Run Control Main” window, click on the “Select Application” button. The “Select an application” window appears as shown below.
2. Select the directory
V:/GLAST/Electronics/TEMPROD/EnvTest/




Figure 22. Select an Application Window

3. Select “biasTest.py”.
4. Click on the “Open” button to open the file.
5. At the “Run Control Main” window, click on the ► button.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.5.2 Monitor Margin and Bias Test Procedure (continued)

- The “Margin and Bias Tests Window” appears as shown below. The indicators following the ranges are clear before the test.




Figure 23. Margin and Bias Tests Window

- Under Mode Select, select TEM/TPS. This selects Mid Range and clears Low Range and High Range.
- Enter the TPS serial number. The TPS serial number is the number on the bar code sticker on the TPS.
- Enter the TEM serial number. The TEM serial number is the number on the bar code sticker on the TEM.
- Click on the “Start” button to run the test. If there are any errors, they will appear in the Messages box and in the log file.

Note: This test takes about 10 seconds to run.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.5.2 Monitor Margin and Bias Test Procedure (continued)

11. Verify that the indicator is green in the Margin and Bias Tests Window, indicating good data (a red light indicates failure of the test) and that no errors appear in the Messages box. **Record** verifications per the data sheet.
12. Open and print the log file (see the sample of the log file below) and attach it to the data cover sheet.




Figure 24. Sample Log File

Note: The test log files are saved as
 C:/TEMPROD/log/EnvTest/bias_TPS#_TEM#_date_time.log. One file is created by running this test.

13. Click on the “Close” button to close the test environment.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.5.3 Temperature Monitor Test Procedure

This section provides instructions to test the TEM temperature monitors.

To setup and run the TEM temperature test:

14. At the “Run Control Main” window.
15. Click on the “Select Application” button. The “Select an application” window appears as shown below.
16. Select the directory
V:/GLAST/Electronics/TEMPROD/EnvTest/




Figure 25. Select an Application Window

17. Select “tempTest.py”
18. Click on the “Open” button to open the file.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.5.3 Temperature Monitor Test Procedure (continued)

19. At the “Run Control Main” window, click on the ► button.
20. The “Temperature Test” Window appears as shown below. The indicator is clear before the test.




Figure 26. Temperature Test

21. Enter the TPS serial number. The TPS serial number is the number on the bar code sticker on the TPS.
22. Enter the TEM serial number. The TEM serial number is the number on the bar code sticker on the TEM.
23. Enter the ambient temperature in Celsius.
24. Click on the “Start” button, to run the test.

Note: This test takes a few seconds to run.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.5.3 Temperature Monitor Test Procedure (continued)

25. Verify that the indicator is green, indicating good data (a red light indicates failure of the test) and that no errors appear in the Messages box. **Record** verifications per the data sheet.
26. Open and print the log file (see the sample log file below) and attach it to the data cover sheet.

Note: The test log files are saved as

C:/TEMPROD/log/EnvTest/temp_TPS#_TEM#_date_time.log.




Figure 27. Sample Temperature Monitor Log File

27. Click on the “Exit” button to close the test environment.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.5.4 Basic Test Procedure

This section provides instructions to test the basic functions of the TEM/TPS unit.

To setup and run the TEM/TPS basic test:

1. At the “Run Control Main” window, click on the “Select Application” button. The “Select an application” window appears as shown below.
2. Select the directory
V:/GLAST/Electronics/TEMPROD/BasicTest/




Figure 28. Select an Application Window

3. Select “basicTest.py”.
4. Click on the “Open” button to open the file.
5. At the “Run Control Main” window, click on the ► button.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.5.4 Basic Test Procedure (continued)

6. The “TEM Basic Test” window appears as shown below. The indicators are clear before the test is run.




Figure 29. TEM Basic Test Window

Note: Do not change the default values and selections in this window; use them as they are.

7. Click on the “Start Test” button.

Note: This test takes about one minute to run. You can click on the “Communication Test” button to view the results as the test is running.

8. Verify that all the indicators are green, indicating good data (a red light indicates failure of the test) and that the value for Communication Errors and Event Errors is “0”. **Record** verifications per the data sheet.

9. Open and print the log file for the test and attach it to the data cover sheet.

Note: The test log files are saved as C:/TEMPROD/log/BasicTest/basic_date_time.log.

10. Click on the “Exit” button to close the test environment.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.5.5 Front End Test Procedure

This section provides instructions to test the TEM without the CAL or TKR front-end electronics.

To setup and run the TEM Front End test.

1. At the “Run Control Main” window, click on the “Select Application” button. The “Select an application” window appears as shown below.
2. Select the directory
V:/GLAST/Electronics/TEMPROD/TemFeTest/




Figure 30. Select an Application Window

3. Select “temFeTest.py”.
4. Click on the “Open” button to open the file.
5. At the “Run Control Main” window, click on the ► button.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.5.5 Front End Test Procedure (continued)

- The “TEM – FE Connectivity Test” window appears as shown below. The indicators are clear before the test.




Figure 31. TEM – FE Connectivity Test Window

Note: Do not change the default values and selections in this window; use them as they are.

- Click on the “Start” button, to run the test.

Note: This test takes about one minute to run.

- Verify that all the indicators are green, indicating good data (a red light indicates failure of the test) and that the value for Total Errors is “0”. **Record** verifications per the data sheet.

- Open and print the log file for the test and attach it to the data cover sheet.

Note: The test file is saved as C:/TEMPROD/Log/TemFeTest/temFe_date_time.log. One log file is created for this test.

- Click on the “Exit” button to exit from the test environment.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.5.6 TEM FIFO Test Procedure

This section provides instructions to test the FIFOs on the TEM.

To setup and run the TEM FIFO monitor test:

1. At the “Run Control Main” window, click on the “Select Application” button. The “Select an application” window appears as shown below.
2. Select the directory
V:/GLAST/Electronics/TEMPROD/FifoTest/




Figure 32. Select an Application Window

3. Select “temFifoTest.py”.
4. Click on the “Open” button to open the file.
5. At the “Run Control Main” window, click on the ► button.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.5.6 TEM FIFO Test Procedure (continued)

- The “TEM FIFO Test” window appears as shown below. The indicators are clear before the test.




Figure 33. TEM FIFO Test Window Selections

Note: Do not change the default values and selections in this window; use them as they are.

- Click on the “Start” button, to run the test.

Note: This test takes a few minutes to run.

- Verify that all the indicators are green, indicating good data (a red light indicates failure of the test) and that the value for Total Errors is “0”. **Record** verifications per the data sheet.

- Open and print the log file and attach it to the data cover sheet.

Note: The test log files are saved as C:/TEMPROD/log/FifoTest/fifo_date_time.log.

- Click on the “Exit” button to exit from the test environment.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.6 Functional Test Procedure

This section provides instructions to test all the function registers on the TEM individually.

To setup and run the TEM environmental monitor test:

1. At the “Run Control Main” window, click on the “Select Application” button. The “Select an application” window appears as shown below.
2. Select the directory
V:/GLAST/Electronics/TEMPROD/FuncTest/




Figure 34. Select an Application Window

3. Select “funcTest.py”.
4. Click on the “Open” button to open the file.
5. At the “Run Control Main” window, click on the ► button.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.6 Functional Test Procedure (continued)

6. The “TEM Functional Tests” window appears as shown below. The indicators are clear before the test.




Figure 35. Functional Tests Window

Note: Do not change the default values and selections in this window; use them as they are.

7. Click on the “Start” button, to run the test.

Note: This test takes 25 minutes to run.

8. Verify that all the indicators are green, indicating good data (a red light indicates failure of the test) and that no errors appear in the Messages box. **Record** verifications per the data sheet.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.6 Functional Test Procedure (continued)

9. Click on the “Close” button to exit from the test environment.
10. Open and print the log file and attach it to the data cover sheet.

Note: The test log files are saved as C:/TEMPROD/log/FuncTest/func_ *date_time*.log.

11. Turn off power supply #1 and 2.
12. Turn off power to the VME Crate.

5.7 Noise Tests

5.7.1 Noise Test Prerequisite

Before this test is run, the RMS meter must be turned on and run for at least 20 minutes.

5.7.2 CAL Noise Test Procedure

This section provides instructions to test the noise on the CAL.

To setup and run the noise test:

1. Verify that the power is off power supply #1 and 2 and the VME Crate.
2. Connect all the equipment and cables per the interconnect drawing in the figure below.




Figure 36. CAL Noise Bias Voltage (HV) Test Setup Interconnection Diagram

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.7.2 CAL Noise Test Procedure (continued)

3. Set the DMM to the auto-ranging setting. Record in the data sheet.
4. Measure DMM lead resistance by connecting the two leads together. Record in the data sheet.
5. Measure the resistance between the UUT chassis and technical ground. Record in the data sheet.
6. Measure the resistance between the test equipment chassis and technical ground. Record in the data sheet.
7. Connect JC-0 to the RMS meter as shown in the figure below following this process:
 - a) Connect the 1 MHz filter (LAT-DS-04767) to J4 of the adaptor (LAT-DS-04820) using a Lemo cable.
 - b) Connect the 1 MHz filter to the RMS meter.
 - c) Connect J1 of the adaptor (LAT-DS-04820) to the connector saver on JC-0 on the TEM.
 - d) Record in the data sheet.




Figure 37. CAL Noise Test Setup—Bias Voltage (HV)

8. Ensure that the RMS meter has been running for 20 minutes.
9. Set the RMS meter to the 1 mV range.
10. Set the function generator to 20 MHz square wave.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.7.2 CAL Noise Test Procedure (continued)

11. Turn on power supply #1 and apply 28.0 volts.
12. Open the “ttermpro” file located in the C:\Program Files\TeraTermProSSH\ directory and connect to the VME Crate using the serial port (COM3).
13. Apply power to the VME Crate.
14. Wait for the boot to finish.
15. Open a Command Prompt window.
16. Change the directory to the following:
V:\GLAST\Electronics\Teststands\gitot
17. Type in “runcontrol.bat” and enter.

5.7.2 CAL Noise Test Procedure (continued)

18. The “Run Control Main” window appears as shown below.




Figure 38. Run Control Main Window

Note: Do not change the options in this window.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.7.2 CAL Noise Test Procedure (continued)

19. At the “Run Control Main” window, click on the “Select Application” button. The “Select an application” window appears as shown below.
20. Select the directory
V:/GLAST/Electronics/TEMPROD/FuncTest/




Figure 39. Select an Application Window

21. Select “funcTest.py”.
22. Click on the “Open” button to open the file.
23. At the “Run Control Main” window, click on the ► button.

5.7.2 CAL Noise Test Procedure (continued)

24. The “TEM Functional Tests” window appears as shown below. The indicators are clear before the test is run.




Figure 40. TEM Functional Tests Window

- 25. Under Tests, clear TEM, TIC, CCC, and TCC.
- 26. Click the “Misc” button.
- 27. Under Misc Tests, select Cal noise.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.7.2 CAL Noise Test Procedure (continued)




Figure 41. TEM Functional Tests Window for CAL Noise Test

28. Click on the “Start” button.
29. While the test is running and after the RMS meter reading has settled, read RMS meter. Record the reading on the data sheet. This is the CAL bias (HV) noise test.
30. Click the “Stop” button to turn off the CAL bias. Record in the data sheet.
31. Verify that the indicator light next to Cal noise turns green. Record in the data sheet.
32. Demate the Lemo cable from J4 of the adaptor.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.7.2 CAL Noise Test Procedure (continued)

33. Connect the Lemo cable to J2 of the adaptor (LAT-DS-04820) as shown in the figure below and record in data sheet.




Figure 42. CAL Noise Test Setup—3.3 Analog Voltage

34. Click the “Start” button in the TEM Functional Tests window.
35. After the RMS meter reading has settled, read the RMS meter. Record the reading on the data sheet. This is the CAL 3.3 analog voltage noise test.
36. Click the “Stop” button to turn off the CAL bias. Record in the data sheet.
37. Verify that the indicator light next to Cal noise turns green. Record in the data sheet.
38. Demate the Lemo cable from J2 of the adaptor (LAT-DS-04820).

5.7.2 CAL Noise Test Procedure (continued)

39. Connect the Lemo cable to J3 of the adaptor (LAT-DS-04820) as shown in the figure below.




Figure 43. CAL Noise Test Setup—3.3 Digital Voltage

40. Click on the “Start” button in the TEM Functional Tests window.
41. After the RMS meter reading has settled, read the RMS meter. Record the reading on the data sheet. This is the CAL 3.3 digital voltage noise test.
42. Click on the “Stop” button to stop the test.
43. Verify that the indicator is green, indicating good data (a red light indicates failure of the test) and that the value for Total Errors is “0”. **Record** verifications per the data sheet.
44. Click the “Close” button to close the test.
45. Open and print the log file for the test and attach it to the data cover sheet.

Note: The test log files are saved as C:/TEMPROD/log/FuncTest/basic_date_time.log.

46. Turn off power supply #1.
47. Turn off power to the VME Crate.
48. Demate the Lemo cable from J3 of the adaptor.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.7.3 TKR Noise Test Procedure

This section provides instructions to test the noise on the TKR.

WARNING: The TEM/TPS internally produces over 50 V at up to 10 mA. Do not manipulate the TEM/TPS or TEM Tester Board during the test procedure. Do not disassemble until the power supplies have been turned off.

To setup and run the noise test:

1. Verify that the power is off power supply #1 and 2 and the VME Crate.
2. Connect all the equipment and cables per the interconnect drawing in the figure below.




Figure 44. TKR Noise Bias Voltage (HV) Test setup Interconnection Diagram

3. Set the DMM to the auto-ranging setting. Record in the data sheet.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.7.3 TKR Noise Test Procedure (continued)

4. Measure DMM lead resistance by connecting the two leads together. Record in the data sheet.
5. Measure the resistance between the UUT chassis and technical ground. Record in the data sheet.
6. Measure the resistance between the test equipment chassis and technical ground. Record in the data sheet.
7. Connect JT-0 to the RMS meter as shown in the figure below following this process:
 - a) Connect the 1 MHz filter (LAT-DS-04767) to J5 of the adaptor (LAT-DS-04821) using a Lemo cable.
 - b) Connect the 1 MHz filter to the RMS meter.
 - c) Connect J1 of the adaptor (LAT-DS-04821) to the connector saver on JT-0 on the TEM.




Figure 45. TKR Noise Test Setup—Bias Voltage (HV)

8. Ensure that the RMS meter has been running for 20 minutes.
9. Set the RMS meter to the 1 mV range.
10. Set the function generator to 20 MHz square wave.
11. Turn on power supply #1 and apply 28.0 volts.
12. Open the “ttermpro” file located in the C:\Program Files\TeraTermProSSH\ directory and connect to the VME Crate using the serial port (COM3).

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.7.3 TKR Noise Test Procedure (continued)

13. Apply power to the VME Crate.
14. Wait for the boot to finish.
15. After the boot-up process for the VME has completed, turn on power supply #2 and apply 3.3 volts.
16. Open a Command Prompt window.
17. Change the directory to the following:
V:\GLAST\Electronics\Teststands\gitot.
18. Type in “runcontrol.bat” and enter.

5.7.3 TKR Noise Test Procedure (continued)

19. The “Run Control Main” window appears as shown below.




Figure 46. Run Control Main Window

Note: Do not change the options in this window.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.7.3 TKR Noise Test Procedure (continued)

20. At the “Run Control Main” window, click on the “Select Application” button. The “Select an application” window appears as shown below.
21. Select the directory
V:/GLAST/Electronics/TEMPROD/FuncTest/




Figure 47. Select an Application Window

22. Select “funcTest.py”.
23. Click on the “Open” button to open the file.
24. At the “Run Control Main” window, click on the ► button.

5.7.3 TKR Noise Test Procedure (continued)

25. The “TEM Functional Tests” window appears as shown below. The indicators are clear before the test is run.




Figure 48. TEM Functional Tests Window

- 26. Under Tests, clear TEM, TIC, CCC, and TCC.
- 27. Click the “Misc” button.
- 28. Under Misc Tests, select Tkr noise.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.7.3 TKR Noise Test Procedure (continued)




Figure 49. TEM Functional Tests Window for TKR Noise Test

29. Click on the “Start” button.
30. While the test is running and after the RMS meter reading has settled, read RMS meter. Record the reading on the data sheet.
31. Click the Stop button to turn off the TKR bias. Record in the data sheet.
32. Verify that the indicator light next to Tkr noise turns green. Record in the data sheet.
33. Demate the Lemo cable from J5 of the adaptor.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.7.3 TKR Noise Test Procedure (continued)

34. Connect the Lemo cable to J2 of the adaptor (LAT-DS-04821) as shown in the figure below.




Figure 50. TKR Noise Test Setup—2.5 Analog Voltage

35. Click the “Start” button in the TEM Functional Tests window.
36. While the test is running, read the RMS meter. Record the reading on the data sheet. This is the TKR 2.5 analog voltage noise test.
37. Click the “Stop” button to turn off the TKR bias. Record in the data sheet.
38. Verify that the indicator light next to Tkr noise turns green. Record in the data sheet.
39. Demate the Lemo cable from J2 of the adaptor.

5.7.3 TKR Noise Test Procedure (continued)

40. Connect the Lemo cable to J3 of the adaptor (LAT-DS-04821) as shown in the figure below.




Figure 51. TKR Noise Test Setup—1.5 Analog Voltage

41. Click on the “Start” button in the TEM Functional Tests window.
42. After the RMS meter reading has settled, read the RMS meter. Record the reading on the data sheet. This is the TKR 1.5 analog voltage noise test.
43. Click the “Stop” button to turn off the Tkr bias. Record in the data sheet.
44. Verify that the indicator light next to Tkr noise turns green. Record in the data sheet.
45. Demate the Lemo cable from J3 of the adaptor.

5.7.3 TKR Noise Test Procedure (continued)

46. Connect the Lemo cable to J4 of the adaptor (LAT-DS-04821) as shown in the figure below.




Figure 52. TKR Noise Test Setup—2.5 Digital Voltage

47. Click on the “Start” button in the TEM Functional Tests window.
48. After the RMS meter reading has settled, read the RMS meter. Record the reading on the data sheet. This is the TKR 2.5 digital voltage noise.
49. Click on the “Stop” button to stop the test.
50. Verify that the indicator is green, indicating good data (a red light indicates failure of the test) and that the value for Total Errors is “0”. **Record** verifications per the data sheet.
51. Click the “Close” button to close the test environment.
52. Open and print the log file for the test and attach it to the data cover sheet.

Note: The test log files are saved as C:/TEMPROD/log/FuncTest/basic_date_time.log.

53. Turn off power supply #1.
54. Turn off power to the VME Crate.
55. Demate the Lemo cable from J4 of the adaptor.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.8 Thermal Vac Test

The Thermal Vac Test runs the following tests together:

- Main Tests
 - Monitor Margin and Bias Midrange – Sets the margin and bias voltages to the nominal (mid) range level and then checks the output reading.
 - Temperature Monitor – Checks the temperature readings.
 - Basic – Checks the basic TEM functions (none of the front end connections).
 - Front End – Checks the front end connections and the front end communication.
 - TEM FIFO – Tests the FIFOs on the TEM
- Functional Tests – Tests all the functional registers on the TEM individually.

5.8.1 Thermal Vac Test Setup Procedure

This section provides instructions to setup the TEM/TPS for the Thermal Vac Test.

To setup the TEM/TPS Main Tests:

1. Verify that the power is off to power supply #1 and the VME Crate.
2. Connect all the equipment and cables per the interconnect drawing in the figure below.

5.8.1: Thermal Vac Test Setup Procedure (continued)




Figure 53. Monitor Margin and Bias Test setup Interconnection Diagram

3. Set the DMM to the auto-ranging setting. Record in the data sheet.
4. Measure DMM lead resistance by connecting the two leads together. Record in the data sheet.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.8.1: Thermal Vac Test Setup Procedure (continued)

5. Measure the resistance between the UUT chassis and technical ground. Record in the data sheet.
6. Measure the resistance between the test equipment chassis and technical ground. Record in the data sheet.
7. Set the function generator to 20 MHz square wave.
8. Turn on power supply #1 and apply 28.0 volts.
9. Open the “ttermpro” file located in the C:\Program Files\TeraTermProSSH\ directory and connect to the crate using the serial port (COM3).
10. Apply power to the VME Crate.
11. Wait for the boot to finish.
12. Disconnect the fan. Record the current draw at external power supply #1 in the data sheet and verify that it is within the specified range.
13. Reconnect the fan.
14. After the boot-up process for the VME has completed turn on power supply #2 and apply 3.3 volts.
15. Open a Command Prompt window.
16. Change the directory to V:\GLAST\Electronics\Teststands\gitot.
17. Type in “runcontrol.bat” and enter.

5.8.1: Thermal Vac Test Setup Procedure (continued)

18. The “Run Control Main” window appears as shown below.




Figure 54. Run Control Main Window

Note: Do not change the options in this window.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.8.1: Thermal Vac Test Setup Procedure (continued)

19. At the “Run Control Main” window, click on the “Select Application” button. The “Select an application” window appears as shown below.
20. Select the directory
V:/GLAST/Electronics/TEMPROD/




Figure 55. Select an Application Window

21. Select “tVacSuite.py”.
22. Click on the “Open” button to open the file.

5.8.1: Thermal Vac Test Setup Procedure (continued)

23. The “Thermal Vac Test Suite Window” appears as shown below. The indicators following the tests are clear before the test.




Figure 56. Thermal Vac Test Suite Window

24. Enter the TPS serial number. The TPS serial number is the number on the bar code sticker on the TPS.
25. Enter the TEM serial number. The TEM serial number is the number on the bar code sticker on the TEM.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.8.1: Thermal Vac Test Setup Procedure (continued)

26. To save the test output in a directory other than the default (C:/TEMPROD/log/tVac/), enter the directory name in the Test Output Directory Name box.
27. Click the Acceptance Mode button.
28. At the “Run Control Main” window, click on the Run ► button.

The suite of tests runs once.

The GUIs from the tests in the suite appear while each test is running.

If the test fails while it is running, a red message box appears. Any errors appear in the Messages box and in the log file. The number of errors is listed in the Suite Errors box.

29. Verify that the Suite Errors box is empty, indicating a passed test. (Any number of errors in the box indicates failure of the test). **Record** the verification on the data sheet.
30. Open and print the log file (see the sample of the log file below) and attach it to the data cover sheet.




Figure 57. Sample Log File

Note: The test log files are saved as
 C:/TEMPROD/log/TestOutputDirectory/SuiteTest/suite_date_time.log.
 The default Test Output Directory is tVac.

31. Click on the “Close” button to close the test environment.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.8.2 Thermal Vac Test Procedure

This section provides instructions to test the TEM/TPS.

To run the TEM/TPS tests:

1. At the “Run Control Main” window, click on the “Select Application” button. The “Select an application” window appears as shown below.
2. Select the directory
V:/GLAST/Electronics/TEMPROD/




Figure 58. Select an Application Window

3. Select “tVacSuite.py”.
4. Click on the “Open” button to open the file.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.8.2: Thermal Vac Test Procedure (continued)

- The “Thermal Vac Test Suite Window” appears as shown below. The indicators following the tests are clear before the test.




Figure 59. Thermal Vac Test Suite Window

- Enter the TPS serial number. The TPS serial number is the number on the bar code sticker on the TPS.
- Enter the TEM serial number. The TEM serial number is the number on the bar code sticker on the TEM.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

5.8.2: Thermal Vac Test Procedure (continued)

8. To save the test output in a directory other than the default (C:/TEMPROD/log/tVac/), enter the directory name in the Test Output Directory Name box.

9. At the “Run Control Main” window, click on the Run ► button.


The GUIs from the tests in the suite appear while each test is running.

If the test fails while it is running, a red message box appears. Any errors will appear in the Messages box and in the log file.

10. At the completion of the Thermal Vac test, in the Thermal Vac Test Suite window, click the Stop button.

11. Verify that the Suite Errors box is empty, indicating a passed test. (Any number of errors in the box indicates failure of the test). **Record** the verification on the data sheet.

12. Open and print the log file (see the sample of the log file below) and attach it to the data cover sheet.



```
suite_20050502_152305.log - Notepad
File Edit Format View Help
15:23:18 do basic test
15:24:17 basic test completed with 0 errors
15:24:17 do temp test
15:24:27 temp test completed with 0 errors
15:24:27 do bias test
15:25:37 bias test completed with 0 errors
15:25:37 do fe test
15:27:16 fe test completed with 0 errors
15:27:16 do fifo test
15:30:07 fifo test completed with 0 errors
15:30:07 do func test
15:35:11 func test completed with 0 errors
15:35:11 suite completed: 1 iteration(s) with 0 error(s)
```

Figure 60. Sample Log File

Note: The test log files are saved as
C:/TEMPROD/log/TestOutputDirectory/SuiteTest/suite_date_time.log.
The default Test Output Directory is tVac.

13. Click on the “Close” button to close the test environment.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

Appendix A (Data Sheets and Covers)

COVER SHEET

Program: GLAST

Procedure Number: LAT-TD-04085

Procedure Title: TEM/TPS Performance Test Procedure

Paragraph Number: _____

Paragraph Title: _____

Unit S/N: _____

TEST READINESS REVIEW COMPLETED AND APPROVED BY THE FOLLOWING:

Test Director: _____ Date: _____

Quality Assurance: _____ Date: _____

Test Conductor: _____ Date: _____

REVIEWED AND APPROVED BY THE FOLLOWING:

Test Director: _____ Date: _____

Quality Assurance: _____ Date: _____

Test Conductor: _____ Date: _____

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

TEM/TPS Performance Test Procedure

| TEST DATA SHEET | | Unit S/N: | Date/Temperature: | |
|-----------------------------|---|---|-----------------------|-----------------|
| Title: 5.1.3 Test Equipment | | Operator: | | QA: |
| Para./ Step | Test Equipment Description, Manufacturer | Model/LAT Number | Serial/Rev. Number | *Cal./Val. Date |
| 5.1.3.1 - 1 | Record Model/LAT number, Serial/Revision number, Calibration due dates and Validation date for all equipment used in this procedure: | | | |
| | VME Crate, Dawn VME Products | 11-1011777-2119 VME64x (series 767) | | |
| | VME, TST-STP Trans card | LAT-DS-00999 | | |
| | VME SBC MVME2304 card, Motorola | PN MVME2304-0123 | | |
| | VME LCB Mezzanine card | LAT-TD-00860 | | |
| | Software for the local PC | LATTE P04-07-02 Downloaded from www-glast.slac.stanford.edu/IntegrationTest/ONLINE/updates/ | | |
| | Software for the local PC | TEMPROD V02-03-01 Found in /nfs/slac/g/glast/online/cvsroot/temprod See TEMPROD/History for more information. | | |
| | DC Power supply #1, BK Precision | BK 1697 | | |
| | DC Power supply #2, BK Precision | BK 1697 | | |
| | 28 Volt supply cable | LAT-DS-03246 | | |
| | PS Control cable | LAT-DS-04831 | | |
| | TEM to GASU cable | LAT-DS-02106 | | |
| | LCB Transition board cable | LAT-DS-03247 | | |
| | TEM Test Board Assembly | LAT-DS-04465 | | |
| | TEM Test board cooling fan assembly | LAT-DS-03567 | | |
| | CAT5 Ethernet cable | TRD855PL-50 | | |
| | RS-232 Cable | TDC003-7 (RECO98M connectors) | | |
| | Ground jumper, Banana, Pomona | B-12-0 | | |

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

TEM/TPS Performance Test Procedure

| TEST DATA SHEET | | Unit S/N: | Date/Temperature: | |
|-----------------------------|---|---------------------|-----------------------|-----------------|
| Title: 5.1.3 Test Equipment | | Operator: | | QA: |
| Para./ Step | Test Equipment Description, Manufacturer | Model/LAT Number | Serial/Rev. Number | *Cal./Val. Date |
| 5.1.3.1 - 1 | Record Model/LAT number, Serial/Revision number, Calibration due dates and Validation date for all equipment used in this procedure: | | | |
| | PS extension cable | LAT-DS-04629 | | |
| | Digital Multimeter, Fluke/Meterman | 87-III/38XR | | |
| | Connector Savers (28 pin), L Com | DGBH28MF | | |
| | Connector Savers (51 pin), Glenair | MWDM2L-51USP1 | | |
| | Connector Savers (69 pin), SLAC | LAT-DS-04724 | | |
| | Connector Savers (78 pin), L Com | DGBH78MF | | |
| | Breakout Box Assembly (BOB) (78 pin), SLAC | LAT-DS-03580 | | |
| | Breakout Cable (BOC), SLAC | LAT-DS-04273 | | |
| | Breakout Cable (BOC), SLAC | LAT-DS-04275 | | |
| | Load | LAT-DS-04822 | | |
| | Load | LAT-DS-04823 | | |
| | 1 MHz Filter | LAT-DS-04767 | | |
| | Noise Measurement Adapter, 51-Pin, SLAC | LAT-DS-04821 | | |
| | Noise Measurement Adapter, 69-Pin, SLAC | LAT-DS-04820 | | |
| | True RMS Volt Meter, Agilent (HP) | 3400A | | |
| | Delay Line, Lemo To Bnc 4N, from SLAC Stores | STORES ID #078697 | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

* This column is used to enter the date that equipment is validated, when validated equipment is recorded in this data sheet.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

TEM/TPS Performance Test Procedure

| TEST DATA SHEET | | Unit S/N: | Date/Temperature: |
|-------------------------------|--|------------|-------------------|
| Title: 5.1.4 Participant List | | Operator: | QA: |
| Para./ Step | Title | Print Name | Signature |
| 5.1.4 - 1 | Record names of all personnel that take part in the test/operation: | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

TEM/TPS Performance Test Procedure

| | TEST DATA SHEET | Unit S/N: | Date: | |
|--------|---|-------------|--------|--------------|
| Title: | 5.2 Pre-Operation Verifications | Operator: | QA: | |
| Step | Description | Requirement | Units | Data |
| 5.2 | Pre-Operation Verifications | | | |
| -1 | Notify QAE. | OK | OK/NG | |
| -2 | Test Readiness Review is done. | OK | OK/NG | |
| -3 | Record the UUT equipment: | | | |
| | TEM Part number | NA | NA | LAT-DS-01481 |
| | TEM Serial number | NA | NA | |
| | TEM LAT Bay location | NA | NA | |
| | TPS Part number | NA | NA | LAT-DS-01482 |
| | TPS Serial number | NA | NA | |
| | TPS LAT Bay location | NA | NA | |
| -4 | Ensure that the LAT or EGSE power is off. | OFF | ON/OFF | |
| -5 | All connector savers are installed on the flight connections. | OK | OK/NG | |
| -6 | The test equipment and participant lists have been completed. | OK | OK/NG | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

TEM/TPS Performance Test Procedure

| TEST DATA SHEET | Unit S/N: | Date/Temperature: | | |
|----------------------------------|--|-------------------|-------|------|
| Paragraph: 5.4 Calibration Tests | | Operator: | QA: | |
| Step | Description | Requirement | Units | Data |
| 5.4.1 | Test: CAL Calibration High Voltage Test Procedure | | | |
| -1 | Verify that the power is off to power supply #1 and the VME Crate. | OK | OK/NG | |
| -3 | Set DMM to autoranging for resistance. | OK | OK/NG | |
| -4 | Measure DMM lead resistance. | < 2.0 | Ω | |
| -5 | Measure BOB to ground. | < 2.0 | Ω | |
| -6 | Remove all shorting plugs from BOBs. | OK | OK/NG | |
| -7 | Measure UUT to ground. | < 2.0 | Ω | |
| -8 | Measure equipment to ground. | < 2.0 | Ω | |
| -9 | Connect BOB and configure DMM. | OK | OK/NG | |
| -31 | Verify the test passed by green indicator and no errors in the Messages box. | OK | OK/NG | |
| -32 | Attach printout of the test log file to this data package. | OK | OK/NG | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

TEM/TPS Performance Test Procedure

| TEST DATA SHEET | Unit S/N: | Date/Temperature: | | |
|----------------------------------|--|-------------------|-------|------|
| Paragraph: 5.4 Calibration Tests | | Operator: | QA: | |
| Step | Description | Requirement | Units | Data |
| 5.4.2 | Test: TRK Calibration High Voltage Test Procedure | | | |
| -1 | Verify that the power is off to power supply #1 and the VME Crate. | OK | OK/NG | |
| -3 | Set DMM to autoranging for resistance. | OK | OK/NG | |
| -4 | Measure DMM lead resistance. | < 2.0 | Ω | |
| -5 | Measure BOB to ground. | < 2.0 | Ω | |
| -6 | Remove all shorting plugs from BOBs. | OK | OK/NG | |
| -7 | Measure UUT to ground. | < 2.0 | Ω | |
| -8 | Measure equipment to ground. | < 2.0 | Ω | |
| -9 | Connect BOB and configure DMM. | OK | OK/NG | |
| -31 | Verify the test passed by green indicator and no errors in the Messages box. | OK | OK/NG | |
| -32 | Attach printout of the test log file to this data package. | OK | OK/NG | |
| - | | | | |
| - | | | | |
| - | | | | |
| - | | | | |

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

TEM/TPS Performance Test Procedure

| TEST DATA SHEET | Unit S/N: | Date/Temperature: | | |
|----------------------------------|--|-------------------|-------|------|
| Paragraph: 5.4 Calibration Tests | | Operator: | QA: | |
| Step | Description | Requirement | Units | Data |
| 5.4.3 | Test: TPS Calibration Tower Current Test Procedure | | | |
| -1 | Verify that the power is off to power supply #1 and the VME Crate. | OK | OK/NG | |
| -2 | Disconnect the Test Board Cooling Fan. | OK | OK/NG | |
| -4 | Set DMM to autoranging for resistance. | OK | OK/NG | |
| -5 | Measure DMM lead resistance. | < 2.0 | Ω | |
| -6 | Measure UUT to ground. | < 2.0 | Ω | |
| -7 | Measure equipment to ground. | < 2.0 | Ω | |
| -28 | Verify the test passed by green indicator and no errors in the Messages box. | OK | OK/NG | |
| -29 | Attach printout of the test log file to this data package. | OK | OK/NG | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

TEM/TPS Performance Test Procedure

| TEST DATA SHEET | | Unit S/N: | Date: | |
|-----------------------|--|---------------|-------|------|
| Title: 5.5 Main Tests | | Operator: | QA: | |
| Step | Description | Requirement | Units | Data |
| 5.5.1 | Main Tests Setup Procedure | | | |
| -34 | Verify that the power is off to power supply #1 and the VME Crate. | OK | OK/NG | |
| -36 | Set DMM to autoranging for resistance. | OK | OK/NG | |
| -37 | Measure DMM lead resistance. | < 2.0 | Ω | |
| -38 | Measure UUT to ground. | < 2.0 | Ω | |
| -39 | Measure equipment to ground. | < 2.0 | Ω | |
| -12 | Record the current draw at the external power supply #1. | 0.100 - 0.130 | Amps | |
| | | | | |
| | | | | |
| | | | | |

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

TEM/TPS Performance Test Procedure

| TEST DATA SHEET | Unit S/N: | Date/Temperature: | | |
|---------------------------|--|-------------------|-------|------|
| Paragraph: 5.5 Main Tests | | Operator: | QA: | |
| Step | Description | Requirement | Units | Data |
| 5.5.2 | Monitor Margin and Bias Test Procedure | | | |
| -11 | Verify the test passed by green indicator and no errors in the Messages box on the Margin and Bias Test window. | OK | OK/NG | |
| -12 | Attach printout of the Monitor Margin and Bias Test log file to this data package. | OK | OK/NG | |
| | | | | |
| 5.5.3 | Temperature Monitor Test | | | |
| -25 | Verify the test passed by green indicator and no errors in the Messages box on the Temperature Tests window. | OK | OK/NG | |
| -26 | Attach printout of the Temperature Monitor Test log file to this data package. | OK | OK/NG | |
| | | | | |
| 5.5.4 | Basic Test | | | |
| -8 | Verify all tests passed by green indicators and "0" for Communication Errors and Event Errors on the Main Panel tab. | OK | OK/NG | |
| -9 | Attach printout of the Basic Test log file to this data package. | OK | OK/NG | |
| | | | | |
| 5.5.5 | Front End Test | | | |
| -8 | Verify all tests passed by green indicators and "0" for Total Errors on the Main Panel tab. | OK | OK/NG | |
| -9 | Attach printout of the Front End Test log file to this data package. | OK | OK/NG | |
| | | | | |
| 5.5.6 | FIFO Test | | | |
| -8 | Verify all tests passed by green indicators and "0" for Total Errors on the FIFO Test window. | OK | OK/NG | |
| -9 | Attach printout of the FIFO Test log file to this data package. | OK | OK/NG | |

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

TEM/TPS Performance Test Procedure

| TEST DATA SHEET | | Unit S/N: | Date/Temperature: | |
|--|---|-------------|-------------------|------|
| Paragraph: 5.6 Functional Test Procedure | | Operator: | QA: | |
| Step | Description | Requirement | Units | Data |
| 5.6 | Functional Test | | | |
| -8 | Verify all tests passed by green indicators and no errors in the Messages box on the Functional Tests window. | OK | OK/NG | |
| -10 | Attach printout of the Functional Test log file to this data package. | OK | OK/NG | |
| | | | | |

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

TEM/TPS Performance Test Procedure

| TEST DATA SHEET | | Unit S/N: | | Date: | |
|------------------------|---|-------------|-------|-------|--|
| Title: 5.7 Noise Tests | | Operator: | | QA: | |
| Step | Description | Requirement | Units | Data | |
| 5.7.2 | CAL Noise Test Procedure | | | | |
| -1 | Verify that the power is off to power supply #1 and 2 and the VME Crate. | OK | OK/NG | | |
| -3 | Set DMM to autoranging for resistance. | OK | OK/NG | | |
| -4 | Measure DMM lead resistance. | < 2.0 | Ω | | |
| -5 | Measure UUT to ground. | < 2.0 | Ω | | |
| -6 | Measure equipment to ground. | < 2.0 | Ω | | |
| -7 | Connect J4 of the adaptor. | OK | OK/NG | | |
| -8 | RMS meter has been running 20 minutes. | OK | OK/NG | | |
| -9 | Set the RMS meter to the 1 mV range. | OK | OK/NG | | |
| -29 | Record the CAL bias (HV) noise. | <500μ | Volts | | |
| -30 | Turn off the CAL bias. | OK | OK/NG | | |
| -31 | Confirm that the light turns green. | OK | OK/NG | | |
| -33 | Connect J2 of the adaptor. | OK | OK/NG | | |
| -35 | Record the CAL 3.3 analog voltage noise. | <150μ | Volts | | |
| -36 | Turn off the CAL bias. | OK | OK/NG | | |
| -37 | Confirm that the light turns green. | OK | OK/NG | | |
| -39 | Connect J3 of the adaptor. | OK | OK/NG | | |
| -41 | Record the CAL 3.3 digital voltage noise. | <200μ | Volts | | |
| -43 | Verify the test passed by green indicator and no errors in the Total Errors box on the Functional Tests window. | OK | OK/NG | | |
| -45 | Attach printout of the test log file to this data package. | OK | OK/NG | | |
| | | | | | |
| | | | | | |
| | | | | | |

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

TEM/TPS Performance Test Procedure

| Step | Description | Requirement | Units | Data |
|------------------------|---|-------------|-------|-------|
| TEST DATA SHEET | | Unit S/N: | | Date: |
| Title: 5.7 Noise Tests | | Operator: | | QA: |
| 5.7.3 | TKR Noise Test Procedure | | | |
| -1 | Verify that the power is off to power supply #1 and 2 and the VME Crate. | OK | OK/NG | |
| -3 | Set DMM to autoranging for resistance. | OK | OK/NG | |
| -4 | Measure DMM lead resistance. | < 2.0 | Ω | |
| -5 | Measure UUT to ground. | < 2.0 | Ω | |
| -6 | Measure equipment to ground. | < 2.0 | Ω | |
| -7 | Connect J5 of the adaptor. | OK | OK/NG | |
| -8 | Ensure that the RMS meter has been running 20 minutes. | OK | OK/NG | |
| -9 | Set the RMS meter to the 1 mV range. | OK | OK/NG | |
| -30 | Record the TKR Bias (HV) noise. | <500μ | Volts | |
| -31 | Turn off the TKR bias. | OK | OK/NG | |
| -32 | Confirm that the indicator light next to Cal noise turns green. | OK | OK/NG | |
| -34 | Connect J2 of the adaptor. | OK | OK/NG | |
| -36 | Record the TKR 2.5 analog voltage noise. | <150μ | Volts | |
| -37 | Turn off the TKR bias. | OK | OK/NG | |
| -38 | Confirm that the indicator light next to Cal noise turns green. | OK | OK/NG | |
| -40 | Connect J3 of the adaptor to the RMS meter. | OK | OK/NG | |
| -42 | Record the TKR 1.5 analog voltage noise. | <150μ | Volts | |
| -43 | Turn off the TKR bias. | OK | OK/NG | |
| -44 | Confirm that the indicator light next to Cal noise turns green. | OK | OK/NG | |
| -46 | Connect J4 of the adaptor. | OK | OK/NG | |
| -48 | Record the TKR 2.5 digital voltage noise. | <150μ | Volts | |
| -50 | Verify the test passed by green indicator and no errors in the Total Errors box on the Functional Tests window. | OK | OK/NG | |

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

TEM/TPS Performance Test Procedure

| TEST DATA SHEET | | Unit S/N: | | Date: | |
|------------------------|---|-------------|-------|-------|--|
| Title: 5.7 Noise Tests | | Operator: | | QA: | |
| Step | Description | Requirement | Units | Data | |
| 5.7.3 | TKR Noise Test Procedure | | | | |
| -52 | Attach printout of the Functional Test log file to this data package. | OK | OK/NG | | |
| | | | | | |
| | | | | | |

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

TEM/TPS Performance Test Procedure

| TEST DATA SHEET | | Unit S/N: | Date: | |
|-----------------------------|--|---------------|-------|------|
| Title: 5.8 Thermal Vac Test | | Operator: | QA: | |
| Step | Description | Requirement | Units | Data |
| 5.8.1 | Thermal Vac Test Setup Procedure | | | |
| -1 | Verify that the power is off to power supply #1 and the VME Crate. | OK | OK/NG | |
| -3 | Set DMM to autoranging for resistance. | OK | OK/NG | |
| -4 | Measure DMM lead resistance. | < 2.0 | Ω | |
| -5 | Measure UUT to ground. | < 2.0 | Ω | |
| -6 | Measure equipment to ground. | < 2.0 | Ω | |
| -12 | Record the current draw at the external power supply #1. | 0.100 - 0.130 | Amps | |
| -29 | Verify that the Suite Errors box is empty, indicating a passed test. | OK | OK/NG | |
| -30 | Attach printout of the Thermal Vac Test log file to this data package. | OK | OK/NG | |
| | | | | |

| TEST DATA SHEET | | Unit S/N: | Date: | |
|-----------------------------|--|-------------|-------|------|
| Title: 5.8 Thermal Vac Test | | Operator: | QA: | |
| Step | Description | Requirement | Units | Data |
| 5.8.2 | Thermal Vac Test Procedure | | | |
| -11 | Verify that the Suite Errors box is empty, indicating a passed test. | OK | OK/NG | |
| -12 | Attach printout of the Thermal Vac Test log file to this data package. | OK | OK/NG | |
| | | | | |

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

Appendix B Connector Mate/Demate Log

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION: _____

| Connector(s) | Authorized by | Date | Mate or De-mate | Flight or Test | Verify Power Off | Pre-mate Inspect | | ESD Bleed and Connector Mate | | Final Inspect Fasteners Torqued, Witness Stripe applied | |
|--------------------------------|-------------------------|-------|-----------------|----------------|------------------|------------------|----|------------------------------|----|---|----|
| | | | | | | Emp. ID# | QA | * Emp ID# | QA | * Emp. ID# | QA |
| Connector Reference Designator | Procedure & para or NCR | M/D/Y | M or D | F or T | Emp. ID# | *Emp. ID# | QA | * Emp ID# | QA | * Emp. ID# | QA |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Note: This Mate/Demate log is a Microsoft Excel file embedded in the Microsoft Word version of this document. The file can be copied and pasted into a folder and then opened as an Excel worksheet.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.