

TPS Subassembly Electrical Interface Continuity and Isolation Test

The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

UNIT DESCRIPTION:

GA12428

CONNECTOR MATE / DEMATE

Connector(s)	Authorized by	Date	Mate or De-mate		Verify or Power Off		Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect	
			M or D	F or T	Emp. ID#	*Emp. ID#	QA	*Emp. ID#	QA	*Emp. ID#	QA	
51	W01678	6/6/05	M	F	SC	SC	W	W	W	W	W	W
52												
53												
54												
55												
56												
57												
58												
55	W01678	6/21/05	D	F	SD	SD	Y	Y	SD	Y	SD	W

\*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:





The Excel Mate/Demate log form that is below is the actual Excel file imported into this Word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

UNIT DESCRIPTION: CONNECTOR MATE / DEMATE  
LCAT 2512

Connector(s)	Authorized by	Date	Mate or De-mate	Flight or Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect	
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID#	QA	*Emp. ID#	QA
Red 150 Connector	W.A.H.78	10/17/05	M	F	LS	LS	LS	LS	LS
SLA Connector									
LCB									
CPS									
CIB									
LCB									
CPS									
Rad									
Rad									
Rad									

\*Personnel that is Mate/Demate certified:

Connector /Bracket R/D:

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

