

TPS Subassembly Electrical Interface Continuity and Isolation Test

The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

UNIT DESCRIPTION: GLAT 2239 **CONNECTOR MATE / DEMATE**

Connector(s)	Authorized by	Date	Mate or De-mate	Flight or Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect Fasteners Torqued, Witness Stripe applied	
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID#	QA	*Emp. ID#	QA
54	PD-4811	9/23/05	M	F	52	52	100%	52	100%
55			M	F					
55			D	F					
55			M	F					
54, 55	721074094405	10/14/05	M	F	52	52	100%	52	100%
54, 55	TD-4811-4812	10/14/05	M	F	52	52	100%	52	100%
54, 55		10/26/05	M	F	52	52	100%	52	100%
54, 55			M	F	52	52	100%	52	100%
54, 55			D	F	52	52	100%	52	100%
54, 55			M	F	52	52	100%	52	100%
54, 55			D	F	52	52	100%	52	100%
54, 55			M	F	52	52	100%	52	100%

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D: