

TPS Subassembly Electrical Interface Continuity and Isolation Test

The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION: GLAT 2234

Connector(s) Connector Reference Designator	Authorized by Procedure & para or NCR	Date M/D/Y	Mate or Demate M or D	Flight or Test F or T	Verify Power Off Emp. ID#	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect Fasteners Torqued, Witness Stripe applied	
						*Emp. ID#	QA	*Emp. ID#	QA	*Emp. ID#	QA
J4	WD1669	10/21	M	F	SD	SD	✓	SD	✓	SD	✓
J5			M				✓		✓		✓
J4			D				✓		✓		✓
J5			D				✓		✓		✓
J4			M				✓		✓		✓
J5			M				✓		✓		✓
J4			D				✓		✓		✓
J5			D				✓		✓		✓
J4	WD1669	11/19/05	M	F	SR	R	✓	SR	✓	R	✓
J4	WD1669	11/15	D	F	SD	SD	✓	SD	✓	SD	✓
J4	WD1669	11/15	M	F	SD	SD	✓	SD	✓	SD	✓
J4	WD1669	11/14	D	F	SD	SD	✓	SD	✓	SD	✓
J4	WD Assembly	11/22	M	F	SD	SD	✓	SD	✓	SD	✓

*Personnel that is Mate/Demate certified.

Connector / Bracket R/D:

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision. LAT-TD-04850-02