

TPS Subassembly Electrical Interface Continuity and Isolation Test

The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION:

LAT 1833

Connector(s)	Authorized by Procedure & para or NCR	Date	Mate or De-mate	Flight or Test	Verify Power Off	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect Fasteners Torqued, Witness Stripe applied
						*Emp. ID#	QA	*Emp. ID#	QA	
JCO		5/1/5	M	F						
JC1										
JC2										
JC3										
JTO										
JTI										
JT2										
JT3										
JT4										
JT5										
JT6										
JT7										
JST										
J1										

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

[Empty box for Connector /Bracket R/D]

TPS Subassembly Electrical Interface Continuity and Isolation Test

The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION: LAT 1833

Connector(s) Connector Reference Designator	Authorized by Procedure & para or NGR	Date M/D/Y	Mate or De-mate M or D	Flight or Test F or T	Verify Power Off Emp. ID#	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect	
						*Emp. ID#	QA	*Emp. ID#	QA	*Emp. ID#	QA
JCO		5/11/5	D	F	JW	JW	JW	JW	JW	JW	JW
JC1											
JC2											
JC3											
JT0											
JT1											
JT2											
JT3											
JT4											
JT5											
JT6											
JT7											
JT8											
JT9											
JT10											

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

TPS Subassembly Electrical Interface Continuity and Isolation Test

The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION: GLAT 1833

Connector(s)	Authorized by Procedure & para or NCR	Date	Mate or De-mate	Flight or Test	Verify Power Off	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect Fasteners Torqued, Witness Stripe applied
						*Emp. ID#	QA	*Emp ID#	QA	
JIC0		5/14/15	M	F						
JIC1										
JIC2										
JIC3										
JIT0										
JIT1										
JIT2										
JIT3										
JIT4										
JIT5										
JIT6										
JIT7										
JIS1										
JIS2										

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D: