## TPS Subassembly Electrical Interface Continuity and Isolation Test

folder and then open it as an Excel worksheet. The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a

## UNIT DESCRIPTION: CONNECTOR MATE / DEMATE 1776 - 67106

,, 1	-	$\overline{}$	_	_	_	Υ	_	_	,	_	_	_	_			
*Personnel that is Mate/Demate certified							J.	4	<b>42</b>	4	L)	<u>J</u>	U P	3)	Connector Reference Designator	Connector(s)
											,	466 Om	WD 872	468 OM	Procedure & para or NCR	Authorized by
							4/11/65	4/11/05	4/10/05	4/10/05	V/X/05	418/105	3)11/05	3/16/05	M/D/Y	Date
							Þ	ρ	M	3	Ø	ρ	Z	3	M or D	Mate or De-mate
							F	f	٦	ה	6	'n	Ð	٦	ForT	Flight or Test
							JSC	276	<b>∑</b> {∟	<b>33</b> %	7,	7	226	J3.L	Етр. ІД#	Verify Power Off
									<b>₹</b> %	356			755	250	*Етр. ID#	Pre-mate inspect
						1.0		4	\$	Q¥.	4	Acr	141	DEV.	QA	Inspect
							•		18C	3 Sc			236	385	• Emp ID#	ESD Bleed and Connector Mate
								Γ'	440	AR		47	4	4	QA	ed and or Mate
													236	755	* Emp. ID#	Final II Fasteners Witness St
						-	本外	4**	A.	4	14	47	Att.	<b>公本</b> C	QA	Final Inspect Fasteners Torqued, Witness Stripe applied

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

LAT-TD-04850

Connector R/D: