

TPS Subassembly Electrical Interface Continuity and Isolation Test

The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

UNIT DESCRIPTION:

LAT 1834

CONNECTOR MATE / DEMATE

Connector(s)	Authorized by	Date	Mate or Demate	Flight or Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect
Connector Reference Designator	Procedure & para or NCR	MM/DD/YY	M or D	F or T	Emp. ID#	*Emp. ID#	*Emp. ID#	*Emp. ID#
IC0	100 W/A	5/11/5	M	F	SW	SW	SW	SW
IC1								
IC2								
IC3								
IC0								
IT1								
IT2								
IT3								
IT4								
IT5								
IT6								
IT7								
IT8								
IT9								

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

5.20.05

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision. LAT-TD-04850-02

TPS Subassembly Electrical Interface Continuity and Isolation Test

The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

UNIT DESCRIPTION: GLAT 1834 **CONNECTOR MATE / DEMATE**

Connector(s)	Authorized by	Date	Mate or Demate	Flight or Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect Fasteners Torqued, Witness Stripe applied
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID#	*Emp. ID#	*Emp. ID#
JC0	WD/da9	5/11/5	D	F	820	820	820	820
JC1								
JC2								
JC3								
DT0								
DT1								
DT2								
DT3								
DT4								
DT5								
DT6								
DT7								
DT8								
DT9								
DT10								
DT11								
DT12								
DT13								
DT14								
DT15								
DT16								
DT17								
DT18								
DT19								
DT20								
DT21								

*Personnel that is Mate/Demate certified:

Connector /Bracket R/D:



5.20.05

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision. LAT-TD-04850-02

TPS Subassembly Electrical Interface Continuity and Isolation Test

The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

UNIT DESCRIPTION: 61AT 1834

CONNECTOR MATE / DEMATE

Connector(s) Connector Reference Designator	Authorized by Procedure & para or NCR	Date M/D/Y	Mate or De-mate M or D	Flight or Test F or T	Verify Power Off Emp. ID#	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect Fasteners Torqued, Witness Stripe applied	
						*Emp. ID#	QA	*Emp. ID#	QA	*Emp. ID#	QA
JC0	WJW	5/12/05	M	F	SW	SW		SW		SW	
JC1											
JC2											
JC3											
DT0											
DT1											
DT2											
DT3											
DT4											
DT5											
DT6											
DT7											
DT8											
DT9											
DT10											

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

5.20.05

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision. LAT-TD-04850-02