

TPS Subassembly Electrical Interface Continuity and Isolation Test

The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

UNIT DESCRIPTION:

6-LAT1738, DT108

CONNECTOR MATE / DEMATE

Connector(s)	Authorized by	Date	Mate or Demate	Flight or Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect
Connector Reference Designator	Procedure & para or NCR	MD/Y	M or D	F or T	Emp. ID#	*Emp. ID#	*Emp. ID#	*Emp. ID#
51	W0832	3/6/05	M	E	536	536	536	536
52	W0832	3/6/05	M	E	536	536	536	536
51	WD944	4/2/05	D	E	536	536	536	536
51		4/7/05	D	E	536	536	536	536
51		4/8/05	M	E	536	536	536	536
52		4/8/05	M	E	536	536	536	536
51		4/11/05	D	E	536	536	536	536
52		4/11/05	D	E	536	536	536	536

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.