TPS Subassembly Electrical Interface Continuity and Isolation Test

folder and then open it as an Excel worksheet. The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a

UNIT DESCRIPTION:

CONNECTOR MATE / DEMATE

*Personnel that is Mate/Demate certified. Connector Reference Designator Connector(s) Procedure & para or NCR 4580m 4580m 4580m 4580m **Authorized** Softe / M/D/Y Date M or D De-mate 003 Mate Flight Test F or T 9 Verify Power Off Emp. ID# þ 2 *Emp. ID# Pre-mate Inspect 600 δ Connector /Bracket * Emp ID# **Connector Mate ESD Bleed and** ζ 6770 R/D: Š * Emp. ID# Witness Stripe applied Fasteners Torqued, Final Inspect Š

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

LAT-TD-04850-02