

TPS Subassembly Electrical Interface Continuity and Isolation Test

The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

UNIT DESCRIPTION:

41AT 1391

CONNECTOR MATE / DEMATE

Connector(s)	Authorized by	Date	Mate or Demate	Flight or Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID#	*Emp ID#	*Emp. ID#
J1	W08302	6/9/05	M	F	JL	JL	JL	JL
J2	W08302A	6/9/05	M	F	JL	JL	JL	JL
J1	re-test	6/13/05	D	F	JL	JL	JL	JL
J2	re-test	6/13/05	D	F	JL	JL	JL	JL
J1	re-test	↓	M	F	JL	JL	JL	JL
J2	re-test	↓	M	F	JL	JL	JL	JL
J1	W08302A	6/13/05	D	F	JL	JL	JL	JL
J2	W08302A	6/13/05	D	F	JL	JL	JL	JL
J1		6/13/05	M	F	JL	JL	JL	JL
J2		6/13/05	M	F	JL	JL	JL	JL
J1	NKRS2a	6/14/05	D	F	JL	JL	JL	JL
J2	NKRS2a	6/14/05	D	F	JL	JL	JL	JL
J1	W08302	7/6/05	D	F	JL	JL	JL	JL
J2	W08302	7/6/05	D	F	JL	JL	JL	JL

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision. LAT-TD-04850-02