



Non conformance report

Pisa 23/10/03 #2

Object:	Al 50mm foil
Drawing	LAT_DS_00303,304,305,306

ID	Description	Action to take
	The Al roll was not properly fixed in the carton box There are evidences of strong deformations	reject



fig.1) The Al roll was shipped by car fixed on a wooden table with care



fig.2) The box was opened in Plyform first time. The Al roll inner cylinder is not regular, indicating shoks.