The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION: G-LAT 1779 (LT109)

Connector(s)	Authorized by	Date	Mate or De-mate	Flight or Test	Verify Power Off	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect Fasteners Torqued, Witness Stripe applied	
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID#	QA	* Emp ID#	QA	* Emp. ID#	QA
J1	W0870	4/12/05	M	F	JJL	JJL	JC/(QA)	JJL	(QA)	JJL	JC/(QA)
J2	W0870	4/12/05	M	F	JJL	JJL	JC/(QA)	JJL	(QA)	JJL	JC/(QA)
J1		4/12/05	M	F	JJL	JJL	JC/(QA)	JJL	(QA)	JJL	JC/(QA)
J1		4/12/05	D	F	JJL		JC (QA)				
J1		4/19/05	D	F	JJL		↓				
J2		4/19/05	D	F	JJL		JC (QA)				
JJL 4/19/05 ~~J2~~											

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

LAT 2 QA

JC 4.20-05