The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION: GLAT 2436

Connector(s)	Authorized by	Date	Mate or De-mate	Flight or Test	Verify Power Off	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect Fasteners Torqued, Witness Stripe applied	
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID#	QA	* Emp ID#	QA	* Emp. ID#	QA
J1-J10	WO 1792	11/14/5	M	F	[illegible]	[illegible]	[illegible]	[illegible]	[illegible]	[illegible]	[illegible]
J1-J10	WO 1792	11/15/5	D	F	[illegible]	[illegible]	[illegible]	[illegible]	[illegible]	[illegible]	[illegible]
J1-J10	1792	11/14/5	M	F	[illegible]	[illegible]	[illegible]	[illegible]	[illegible]	[illegible]	[illegible]

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D: