# CONNECTOR MATE / DEMATE

**UNIT DESCRIPTION:** HCB GLAT2437

| Connector(s) | Authorized by | Date | Mate or De-mate | Flight or Test | Verify Power Off | Pre-mate Inspect | | ESD Bleed and Connector Mate | | Final Inspect Fasteners Torqued, Witness Stripe applied | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Connector Reference Designator | Procedure & para or NCR | M/D/Y | M or D | F or T | Emp. ID# | *Emp. ID# | QA | * Emp ID# | QA | * Emp. ID# | QA |
| J1 - J10 | WO1793 | 11/14/05 | M | F | [illegible] | [illegible] | [illegible] | [illegible] | [illegible] | [illegible] | [illegible] |
| J1 - J10 | WO1793 | 11/15/05 | D | F | [illegible] | [illegible] | [illegible] | [illegible] | [illegible] | [illegible] | [illegible] |
| J1 - J10 | ↓ | 12/15/05 | M | F | [illegible] | [illegible] | [illegible] | [illegible] | [illegible] | [illegible] | [illegible] |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D: