The Excel Mate/Demate log form that is below is the actual Excel file imported into this Word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION: GCAT2228

Connector(s)	Authorized by	Date	Mate or De-mate	Flight or Test	Verify Power Off	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect Fasteners Torqued, Witness Stripe applied	
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID#	QA	* Emp ID#	QA	* Emp. ID#	QA
LCB Backplane	V.O. 1715	10/17/05	M	F	L.S	C.S	[illegible]	C.S	[illegible]	L.S	[illegible]
↓	↓	↓	D	↓	L.S		[illegible]		[illegible]	↓	[illegible]

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D: