Appendix C: Connector Mate/Demate Log

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION: GCAT 2231

Connector(s)	Authorized by	Date	Mate or De-mate	Flight or Test	Verify Power Off	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect Fasteners Torqued, Witness Stripe applied	
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp ID#	*Emp ID#	QA	* Emp ID#	QA	* Emp. ID#	QA
LCB Backplane	W.O. 1765	2/7/96	M	F	L.S	L.S	✓	L.S	✓	L.S	✓
1/	↓	↓	D	↓	↓					L.S	✓

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Note: This Mate/Demate log is a Microsoft Excel file embedded in the Microsoft Word version of this document. The file can be copied and pasted into a folder and then opened as an Excel worksheet.

Appendix C: Connector Mate/Demate Log

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION: GCAT2231

Connector(s)	Authorized by	Date	Mate or De-mate	Flight or Test	Verify Power Off	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect Fasteners Torqued, witness Stripe applied	
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp ID#	QA	* Emp ID#	QA	* Emp ID#	QA
Backplane LCB	W.O.1711	10/19/20	M	F	L.S	L.S	✓	L.S	✓	L.S	✓
"	"	"	D	F	L.S					L.S.	

*Personnel that is Mate/Demate certified

Connector /Bracket R/D:

Note: This Mate/Demate log is a Microsoft Excel file embedded in the Microsoft Word version of this document. The file can be copied and pasted into a folder and then opened as an Excel worksheet.