The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION: GLAT 1782

Connector(s)	Authorized by	Date	Mate or De-mate	Flight or Test	Verify Power Off	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect Fasteners Torqued, Witness Stripe applied	
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID#	QA	* Emp ID#	QA	* Emp. ID#	QA
J1		5/11/5	M	F	[illegible]	[illegible]	JC [illegible]	[illegible]	JC [illegible]	[illegible]	JC [illegible]
J2		5/11/5	M	F	[illegible]	[illegible]		[illegible]		[illegible]	
J2		5/12/5	D	F	[illegible]	[illegible]		[illegible]		[illegible]	
J2		5/12/5	M	F	[illegible]	[illegible]		[illegible]		[illegible]	
J1		5/12/5	D	F	[illegible]	[illegible]		[illegible]		[illegible]	
J2		5/12/5	D	F	[illegible]	[illegible]	JC [illegible]	[illegible]	J [illegible]	[illegible]	JC [illegible]

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

LAT 2 QA

5.13.05