The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

ORIGINAL LOST

Recreated from WO history.

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION: GLAT 178T (GT115)

Connector(s)	Authorized by	Date	Mate or De-mate	Flight or Test	Verify Power Off	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect Fasteners Torqued, Witness Stripe applied	
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID#	QA	* Emp ID#	QA	* Emp. ID#	QA
J1	W0872	5/19/05	M	F	[illegible]	[illegible]		[illegible]		[illegible]	
J2	W0872	5/19/05	M	F	[illegible]	[illegible]		[illegible]		[illegible]	
J1		5/25/05	D	F	[illegible]		LAT 14 QA		LAT 14 QA		
J2		5/25/05	D	F	[illegible]						LAT 14 QA

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D: