The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

ORIGINAL LOST

Recreated from WO history

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION: GLAT1786 (GT1(6)

Connector(s)	Authorized by	Date	Mate or De-mate	Flight or Test	Verify Power Off	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect Fasteners Torqued, Witness Stripe applied	
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID#	QA	* Emp ID#	QA	* Emp. ID#	QA
J1	WO872	5/20/07	M	F	JL	JL		JL		JL	
J2	WO872	5/20/07	M	F	JL	JL		JL		JL	
J1		5/24/07	D	F			LAT 14 QA		LAT 14 QA		LAT 14 QA
J2		5/24/07	D	F							

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D: