The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION: GLAT1781

Connector(s)	Authorized by	Date	Mate or De-mate	Flight or Test	Verify Power Off	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect Fasteners Torqued, Witness Stripe applied	
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID#	QA	* Emp ID#	QA	* Emp. ID#	QA
J1		5/9/5	M	F	SW	SW	JC/[illegible]	SW	JC/[illegible]	SW	JC/[illegible]
J2		5/9/5	M	F	SW	SW		SW		SW	
J2		5/10/5	D	F	SW	SW		SW		SW	
J2		5/12/5	M	F	SW	SW		SW		SW	
J1		5/12/5	D	F	SW	SW		SW		SW	
J2		5/12/5	D	F	SW	SW	JC/[illegible]	SW	JC/[illegible]	SW	JC/[illegible]

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

LAT 2 QA

5-12-05