Appendix B Connector Mate/Demate Log

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION: GLAT 1783 (GT103)

Connector(s)	Authorized by	Date	Mate or De-mate	Flight or Test	Verify Power Off	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect Fasteners Torqued, Witness Stripe applied	
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID#	QA	* Emp ID#	QA	* Emp. ID#	QA
J1	WO 872	5/27/05	M	F	JJC	JJC	JC (EW)	JC	JC (EW)	JC	(EW) JC
J2	↓	5/27/05	M	F	JJC	JJC	JC (EW)	JC	JC (EW)	JC	(EW) JC
J1	WO 872	5/27/05	D	F	JJC						
J2	↓	6/1/05	D	F	JJC						
J1	WO 872	6/1/05	M	F	JJC						
J1	↓	6/1/05	D	F	JJC						

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D: [ ]

Note: This Mate/Demate log is a Microsoft Excel file embedded in the Microsoft Word version of this document. The file can be copied and pasted into a folder and then opened as an Excel worksheet.