The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION: GLAT1777

Connector(s)	Authorized by	Date	Mate or De-mate	Flight or Test	Verify Power Off	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect Fasteners Torqued, Witness Stripe applied	
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID#	QA	* Emp ID#	QA	* Emp. ID#	QA
J1	W0872	6/29/05	M	F	[illegible]	[illegible]	LAT 14 QA	[illegible]	LAT 14 QA	[illegible]	LAT 14 QA
J2	W0872	6/29/05	M	F	[illegible]	[illegible]	LAT 14 QA	[illegible]	LAT 14 QA	[illegible]	LAT 14 QA
J1	Test	6/30/05	D	F	[illegible]						
J1	test	6/30/05	M	F	[illegible]	[illegible]	LAT 14 QA	[illegible]	LAT 14 QA	[illegible]	LAT 14 QA
J1	W0878	6/30/05	D	F	[illegible]						
J2	W0878	6/30/05	D	F	[illegible]						

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D: [ ]