

Appendix C: Connector Mate/Demate Log

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION: CLAT221A

Connector(s)	Authorized by Procedure & para or NCR	Date M/D/Y	Mate or De-mate M or D	Flight or Test F or T	Verify Power Off Emp. ID#	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect	
						*Emp. ID#	QA	*Emp. ID#	QA	*Emp. ID#	QA
Connector Reference Designator <u>SIB Backplane</u>	<u>W.077A</u>	<u>11/14/07</u>	<u>M</u>	<u>F</u>	<u>LS</u>	<u>LS</u>	<u>LS</u>	<u>LS</u>	<u>LS</u>	<u>LS</u>	<u>LS</u>

*Personnel that is Mate/Demate certified.

Connector /Bracket **R/D:**

Note: This Mate/Demate log is a Microsoft Excel file embedded in the Microsoft Word version of this document. The file can be copied and pasted into a folder and then opened as an Excel worksheet.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

Appendix C: Connector Mate/Demate Log

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION:

C1A12210

Connector(s)	Authorized by	Date	Mate or Demate	Flight Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect Fasteners Torqued, Witness Stroke applied
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID#	QA	*Emp. ID#
SIB acceptable	WA. 1718	10/2/15	N	F	C.S	C.S	Y	C.S
			D	F	C.S		Y	C.S

*Personnel that is Mate/Demate certified.

Note: This Mate/Demate log is a Microsoft Excel file embedded in the Microsoft Word version of this document. The file can be copied and pasted into a folder and then opened as an Excel worksheet.