

Appendix C: Connector Mate/Demate Log

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION: GLAT 2241

Connector(s)	Authorized by Procedure & para or NCR	Date	Mate or De-mate M or D	Flight or Test F or T	Verify Power Off Emp ID#	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect	
						*Emp. ID#	QA	*Emp ID#	QA	*Emp. ID#	QA
Connector Reference Designator		MIDY									
J4	WB 1700	1/19/16	M	F	8	8	YL	8	YL	8	YL
J5			M								
J4			D								
J5			D								
J4			M								
J5			M								
J4			D								
J5			D								

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Note: This Mate/Demate log is a Microsoft Excel file embedded in the Microsoft Word version of this document. The file can be copied and pasted into a folder and then opened as an Excel worksheet.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

TPS Subassembly Electrical Interface Continuity and Isolation Test

The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION: 6212241

Connector(s)	Authorized by Procedure & para or NCR	Date M/D/Y	Mate or De-mate M or D	Flight or Test F or T	Verify Power Off Emp. ID#	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect	
						*Emp. ID#	QA	*Emp ID#	QA	*Emp. ID#	QA
21	100740	10/27/08	M	F	27	Y	27	Y	27	Y	Y
25			D	F		Y					Y
25			D	F		Y					Y
24			M	F							
25			M	F							
24			D	F							
25			D	F							

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D: