

Appendix C: Connector Mate/Demate Log

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION:

GAT22C

Connector(s) Connector Reference Designator	Authorized by Procedure & para or NCR	Date M/D/Y	Mate or De-mate M or D	Flight or Test F or T	Verify Power Off Emp. ID#	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect	
						*Emp. ID#	QA	*Emp. ID#	QA	*Emp. ID#	QA
SIB Connector	W01803	11/18/13	M	F	CS	CS	Y	CS	CS	CS	Y
		11/19/13	D	F	CS	CS	Y	CS	CS	CS	Y
		11/19/13	D	F	CS	CS	Y	CS	CS	CS	Y
		11/19/13	D	F	CS	CS	Y	CS	CS	CS	Y

\*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Note: This Mate/Demate log is a Microsoft Excel file embedded in the Microsoft Word version of this document. The file can be copied and pasted into a folder and then opened as an Excel worksheet.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

Appendix C: Connector Mate/Demate Log

CONNECTOR MATE / DEMATE

SCAT222

UNIT DESCRIPTION:

Connector(s) Connector Reference Designator	Authorized by Procedure & para or NCR	Date M/D/Y	Mate or De-mate M or D	Flight or Test F or T	Verify Power Off Emp. ID#	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect	
						*Emp. ID#	QA	*Emp. ID#	QA	*Emp. ID#	QA
SIB <i>Boeing/Boeing</i>	<i>W.C. [Signature]</i>	<i>11/18/05</i>	<i>M</i>	<i>F</i>	<i>6-5</i>	<i>VC</i>	<i>6-5</i>	<i>VC</i>	<i>6-5</i>	<i>VC</i>	

Connector /Bracket R/D:

\*Personnel that is Mate/Demate certified.

Note: This Mate/Demate log is a Microsoft Excel file embedded in the Microsoft Word version of this document. The file can be copied and pasted into a folder and then opened as an Excel worksheet.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.