

Appendix C: Connector Mate/Demate Log

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION: GLAT 2825

Connector(s) Connector Reference Designator	Authorized by Procedure & para or NCR	Date M/D/Y	Mate or De-mate M or D	Flight or Test F or T	Verify Power Off Emp. ID#	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect	
						*Emp. ID#	QA	*Emp. ID#	QA	*Emp. ID#	QA
SIB CR 44	1.01757	7/14/08	M	F	1.5	YU	1.5	YU	1.5	YU	YU
LCB BACU P100			M	F	1.5	YU	1.5	YU	1.5	YU	YU
SIB			M	F	1.5	YU	1.5	YU	1.5	YU	YU
CPS			M	F	1.5	YU	1.5	YU	1.5	YU	YU
Rad750 -11			M	F	1.5	YU	1.5	YU	1.5	YU	YU
73			M	F	1.5	YU	1.5	YU	1.5	YU	YU
74			M	F	1.5	YU	1.5	YU	1.5	YU	YU
77			M	F	1.5	YU	1.5	YU	1.5	YU	YU
74			M	F	1.5	YU	1.5	YU	1.5	YU	YU
Rad750 BACU P100			M	F	1.5	YU	1.5	YU	1.5	YU	YU

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Note: This Mate/Demate log is a Microsoft Excel file embedded in the Microsoft Word version of this document. The file can be copied and pasted into a folder and then opened as an Excel worksheet.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

Appendix C: Connector Mate/Demate Log

CONNECTOR MATE / DEMATE

GCATZ

UNIT DESCRIPTION:

Connector(s) Connector Reference Designator	Authorized by Procedure & para or NCR	Date	Mate or Demate M or D	Flight or Test F or T	Verify Power Off Emp. ID#	Pre-mate inspect		ESD Bleed and Connector Mate		Final Inspect Fasteners Torqued, Wireless Scribe applied	
						*Emp. ID#	QA	*Emp. ID#	QA	*Emp. ID#	QA
Rad 250 connectors 32	WFB	3/29/6	M	F	CS	CS	CS	CS	CS	CS	CS
34	V	↓	↓	↓	↓	↓	↓	↓	↓	↓	↓

*Personnel that is Mate/Demate certified.

Connector R/D: /Bracket

Note: This Mate/Demate log is a Microsoft Excel file embedded in the Microsoft Word version of this document. The file can be copied and pasted into a folder and then opened as an Excel worksheet.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

Appendix C: Connector Mate/Demate Log

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION: ~~SCA#12~~ SCA7025

Connector(s) Connector Reference Designator	Authorized by Procedure & para or NCR	Date	Mate or De-mate M or D	Flight or Test F or T	Verify Power Off Emp. ID#	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect	
						*Emp. ID#	QA	*Emp. ID#	QA	*Emp. ID#	QA
CRate ICB Backup plate SIB CPS Rad 750 23 24	WATTS	7/26/06	M	F	K.S	LS	YU	LS	YU	LS	YU
		↓	↓	↓	↓	↓	↓	↓	↓	↓	↓
		↓	↓	↓	↓	↓	↓	↓	↓	↓	↓
		↓	↓	↓	↓	↓	↓	↓	↓	↓	↓
CCA ICB Backup plate SIB CPS	W.A.173	↓	↓	↓	↓	↓	YU	↓	YU	↓	YU
		↓	↓	↓	↓	↓	↓	↓	↓	↓	↓
		↓	↓	↓	↓	↓	↓	↓	↓	↓	↓
		↓	↓	↓	↓	↓	↓	↓	↓	↓	↓
CRate ICB Backup plate SIB CPS	W.A.173	↓	M	↓	↓	↓	YU	↓	YU	↓	YU
		↓	↓	↓	↓	↓	↓	↓	↓	↓	↓
		↓	↓	↓	↓	↓	↓	↓	↓	↓	↓
		↓	↓	↓	↓	↓	↓	↓	↓	↓	↓

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Note: This Mate/Demate log is a Microsoft Excel file embedded in the Microsoft Word version of this document. The file can be copied and pasted into a folder and then opened as an Excel worksheet.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

Appendix C: Connector Mate/Demate Log

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION: GLAT321

Connector(s)	Authorized by Procedure & para of NCR	Date	Mate or De-mate	Flight or Test	Verify Power Off	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect	
						*Emp. ID#	QA	*Emp ID#	QA	*Emp ID#	QA
Connector Reference Designator 73 74	W.O. 175 1	7/16/16	M	F	65					65	72
										65	72

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Note: This Mate/Demate log is a Microsoft Excel file embedded in the Microsoft Word version of this document. The file can be copied and pasted into a folder and then opened as an Excel worksheet.