

TPS Subassembly Electrical Interface Continuity and Isolation Test

The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

**CONNECTOR MATE / DEMATE**

UNIT DESCRIPTION: TPS SN#2

Connector(s)	Authorized by Procedure & para or NCR	Date	Mate or De-mate M or D	Flight or Test F or T	Verify Power Off Emp. ID#	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect	
						*Emp. ID#	QA	*Emp. ID#	QA	*Emp. ID#	QA
31 Connector Reference Designator	LAT-TD-04850 LAT-TD-04850	12/15/04 12/15/04	M M	F F	240079 240079	LAT TO	240079 240079	LAT TO	240079 240079	LAT TO	QA QA

\*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Tower Electronics Module Electrical Interface Continuity and Isolation Test

The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

UNIT DESCRIPTION:

CONNECTOR MATE / DEMATE

Connector(s)	Authorized by	Date	Mate or Demate	Flight or Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID#	*Emp ID#	*Emp. ID#
218	LAT-PS-0468	12/10/04	M	F	00449761	00514974	00449761	00449761
219								
220								
221								
222								
223								
224								
225								
226								
227								
228								
229								
230								
231								
232								
233								
234								
235								

\*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

Tower Electronics Module Stray Voltage Test

The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

**UNIT DESCRIPTION:** TEAM 1-611

**CONNECTOR MATE / DEMATE**

Connector(s)	Authorized by	Date	Mate or Demate	Flight or Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect	
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID#	QA	*Emp. ID#	QA
I1	NCMR2121	12/22/04	D	F	240079	240079	LAT 10 QA	240079	LAT 10 QA

\*Personnel that is Mate/Demate certified. Connector /Bracket R/D:

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

# SLAC-GLAST CONNECTOR MATE / DE-MATE LOG

This log records mate and de-mate events for ONE (1) TPS Assembly, through completion of assembly and test activities performed on the indicated Work Order. For further records refer to logs associated with Work Orders applicable to part number LAT-DS-02388.

**TPS ASSY PN: LAT-DS-01482** WORK ORDER NO.: F17300

SERIAL NUMBER: G-LAT1744

REF	DATE	MATE / DE-MATE EVENT	OCCURRENCES	BY
J1		Demate to Assemble Lid	1	
J2		Demate to assemble chassis	1	
J2		<del>Do</del> Demate and mate to assemble screws	1	

Tower Electronics Module Subassembly Stray Voltage Test

The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

UNIT DESCRIPTION: 6-LAT1753 **CONNECTOR MATE / DEMATE**  
Connector save mate

Connector(s)	Authorized by	Date	Mate or Demate	Flight or Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID#	*Emp ID#	Fasteners Torqued, Witness Stamp applied
351		1/27/05	M	F	351			
351								
351								
351								
351								
351								
351								
351								
351								
351								
351								
351								
351								
351								
351								
351								
351								
351								
351								
351								
351								
351								
351								
351								

\*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:



Tower Electronics Module Electrical Interface Continuity and Isolation Test

The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

UNIT DESCRIPTION: \_\_\_\_\_

**CONNECTOR MATE / DEMATE**

Connector(s) Connector Reference Designator	Authorized by Procedure & para or NCR	Date M/D/Y	Mate or De-mate M or D	Flight or Test F or T	Verify Power Off Emp. ID#	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect Fasteners Torqued, Witness Stripe applied	
						* Emp. ID#	QA	* Emp. ID#	QA	* Emp. ID#	QA
DC1		11/27/05	D	F	SL	SL				DC1	
DC2											
DC3											
DC4											
DT1											
DT2											
DT3											
DT4											
DT5											
DT6											
DT7											
DT8											
DC2											

\*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.