

Tower Electronics Module Subassembly Stray Voltage Test

The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION:

6LAT1754 Connector Seven demate

Qual

Connector(s)	Authorized by Procedure & para or NCR	Date M/D/Y	Mate or De-mate M or D	Flight or Test F or T	Verify Power Off Emp. ID#	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect	
						*Emp. ID#	QA	*Emp ID#	QA	*Emp. ID#	QA
5S1		11/27/05	D	F	JSL		4FC				
5S2											
5S3											
5S4											
5T1											
5T2											
5T3											
5T4											
5T5											
5T6											
5T7											
5T8											
5A											



Connector /Bracket R/D:

*Personnel that is Mate/Demate certified.

Tower Electronics Module Stray Voltage Test

The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

Re: ribe, ~~mate~~ demate connector savers

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION: *TEM/TPS LAT-DS-01643 S/N GLAT 1754*

1-21-04
N/A *AFC*
1-21-04

Connector(s)	Authorized by Procedure & para or NCR	Date	Mate or De-mate M or D	Flight or Test F or T	Verify Power Off	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect	
						*Emp. ID#	QA	*Emp. ID#	QA	*Emp. ID#	QA
Connector Reference Designator	TD-04085	1/21/05	D	F	L.S.	L.S.	AFC	L.S.	AFC	AFC	AFC
JT5											
JC3											
JT6											
JT7											
JC4											
JT8											
JT1											
JC1											
JT2											
JT3											
JS1											
JC2											
JT4											

*Personnel that is Mate/Demate certified. Connector /Bracket R/D:

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

Tower Electronics Module Electrical Interface Continuity and Isolation Test

The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

UNIT DESCRIPTION: TEM/IPS GLAT 1754 connector save mate, Post-Vibe

Connector(s)	Authorized by Procedure & para or NCR	Date	Mate or De-mate M or D	Flight or Test F or T	Verify Power Off	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect	
						*Emp. ID#	QA	*Emp ID#	QA	*Emp. ID#	QA
Connector Reference Designator											
531		1/25/05	M	F	7SL	SS	APC				
501											
502											
503											
504											
5T1											
5T2											
5T3											
5T4											
5T5											
5T6											
5T7											
5T8											
52											

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

Tower Electronics Module Electrical Interface Continuity and Isolation Test

The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

CONNECTOR MATE / DEMATE
GLAT 1754 (QUAL UNIT)

UNIT DESCRIPTION:

Connector(s) Connector Reference Designator	Authorized by Procedure & para or NCR	Date MD/Y	Mate or De-mate M or D	Flight or Test F or T	Verify Power Off Emp. ID#	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect Fasteners Torqued, Witness Stripe applied	
						*Emp. ID#	QA	*Emp. ID#	QA	*Emp. ID#	QA
J1 (TPS)		4/6/05	D	F	JLC	JLC	JLC	JLC	JLC	JLC	JLC
J2 (TPS)		↓	↓	↓	↓	↓	↓	↓	↓	↓	↓
J1 (TEM)		4/6/05	M	F	JLC	JLC	JLC	JLC	JLC	JLC	JLC
J2 (TPS)		4/8/05	M	F	JLC	JLC	JLC	JLC	JLC	JLC	JLC
J3 (TPS)											

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.