

TPS Subassembly Electrical Interface Continuity and Isolation Test

The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION:

GATTI775, GTD5

| Connector(s) | Authorized by | Date | Mate or Demate | Flight or Test | Verify Power Off | Pre-mate Inspect | ESD Bleed and Connector Mate | Final Inspect |
|--------------------------------|-------------------------|---------|----------------|----------------|------------------|------------------|------------------------------|---------------|
| Connector Reference Designator | Procedure & para or NCR | M/D/Y | M or D | F or T | Emp. ID# | * Emp. ID# | * Emp. ID# | * Emp. ID# |
| 21 | W0832 | 3/16/05 | M | F | 53C | 53C | 53C | 53C |
| 21 | W0832 | 3/16/05 | M | F | 53C | 53C | 53C | 53C |
| 21 | W0994 | 4/21/05 | D | F | 53C | 53C | 53C | 53C |
| 21 | | 4/21/05 | M | F | 53C | 53C | 53C | 53C |
| 21 | | 4/10/05 | M | F | 53C | 53C | 53C | 53C |
| 22 | | 4/10/05 | M | F | 53C | 53C | 53C | 53C |
| 21 | | 4/11/05 | D | F | 53C | 53C | 53C | 53C |
| 22 | | 4/10/05 | D | F | 53C | 53C | 53C | 53C |

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.