

Tower Electronics Module Electrical Interface Continuity and Isolation Test

The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

UNIT DESCRIPTION: CONNECTOR MATE / DEMATE
04A1758 (67107)

Connector(s)	Authorized by	Date	Mate or De-mate	Flight or Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect
Connector Reference Designator	Procedure & para or NGR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID# QA	*Emp. ID# QA	*Emp. ID# QA
51								
5C0	W0830	4/6/05	D	F	356	356	472	356
5C1								
5C2								
5C3								
5T0								
5T1								
5T2								
5T3								
5T4								
5T5								
5T6								
5T7								
5S1								

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

TPS Subassembly Electrical Interface Continuity and Isolation Test

The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

UNIT DESCRIPTION: 6LAT1758 (GT107) **CONNECTOR MATE / DEMATE**

Connector(s)	Authorized by	Date	Mate or Demate	Flight or Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect
Connector Reference Designator	Procedure & para or NCR	MDY	M or D	F or T	Emp. ID#	*Emp. ID# QA	*Emp ID# QA	*Emp. ID# QA
JT0	W2820	3/25/15	M	F	PAH	PAH QA	PAH QA	PAH QA
JT1								
JT2								
JT3								
JT4								
JT5								
JT6								
JT7								
JC0								
JC1								
JC2								
JC3								
JS1								
J/								

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.