

Tower Electronics Module Electrical Interface Continuity and Isolation Test

The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION: LAT 1035

Connector(s) Connector Reference Designator	Authorized by Procedure & para or NCR	Date MD/Y	Mate or De-mate M or D	Flight or Test F or T	Verify Power Off Emp. ID#	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect	
						*Emp. ID#	QA	*Emp. ID#	QA	*Emp. ID#	QA
JC-0	WOLBY	5/15	M	F	SP	SP	SP	SP	SP	SP	SP
JC-1											
JC-2											
JC-3											
JT-0											
JT-1											
JT-2											
JT-3											
JT-4											
JT-5											
JT-6											
JT-7											
J-1											
JS-1											

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

Tower Electronics Module Electrical Interface Continuity and Isolation Test

The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION: LAT 1835

Connector(s)	Authorized by Procedure & para or NCR	Date M/D/Y	Mate or De-mate M or D	Flight or Test F or T	Verify Power Off Emp. ID#	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect Fasteners Torqued, Witness Stripe applied	
						*Emp. ID#	QA	*Emp ID#	QA	* Emp. ID#	QA
Connector Reference Designator	WDBWA	5/10/15	D	F	805	805	805	805	805	805	805
JIC-0											
JIC-1											
JIC-2											
JIC-3											
JIT-0											
JIT-1											
JIT-2											
JIT-3											
JIT-4											
JIT-5											
JIT-6											
JIT-7											
JIT-8											
JIT-9											
JIT-10											
JIT-11											
JIT-12											
JIT-13											
JIT-14											
JIT-15											
JIT-16											
JIT-17											
JIT-18											
JIT-19											
JIT-20											
JIT-21											
JIT-22											
JIT-23											
JIT-24											
JIT-25											
JIT-26											
JIT-27											
JIT-28											
JIT-29											
JIT-30											
JIT-31											
JIT-32											
JIT-33											
JIT-34											
JIT-35											
JIT-36											
JIT-37											
JIT-38											
JIT-39											
JIT-40											
JIT-41											
JIT-42											
JIT-43											
JIT-44											
JIT-45											
JIT-46											
JIT-47											
JIT-48											
JIT-49											
JIT-50											
JIT-51											

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Tower Electronics Module Electrical Interface Continuity and Isolation Test

The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION: GLAT 1835

Connector(s) Connector Reference Designator	Authorized by Procedure & para or NCR	Date MD/Y	Mate or De-mate M or D	Flight or Test F or T	Verify Power Off Emp. ID#	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect Fasteners Torqued, Witness Strips applied * Emp. ID#
						*Emp. ID#	QA	*Emp. ID#	QA	
JC-0	W069 S135	5/13/15	M	F	DD	DA	135	DA	135	DA
JC-1										
JC-2										
JC-3										
JT-0										
JT-1										
JT-2										
JT-3										
JT-4										
JT-5										
JT-6										
JT-7										
J-1										
J81										

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.