

TEM/TPS Performance Test Procedure

Appendix B Connector Mate/Demate Log

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION:

GLAT 1837

Connector(s) Connector Reference Designator	Authorized by Procedure & para or NCR	Date M/D/Y	Mate or De-mate M or D	Flight or Test F or T	Verify Power Off Emp. ID#	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect Fasteners Torqued, Witness Stripe applied * Emp. ID#
						*Emp. ID#	DA	*Emp. ID#	DA	
JC-0	Franklin	6/4/5	M	F	80	80	DA	DA	80	DA
JC-1										
JC-2										
JC-3										
JT-0										
JT-1										
JT-2										
JT-3										
JT-4										
JT-5										
JT-6										
JT-7										
JT-2										
JT-1										

\*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Note: This Mate/Demate log is a Microsoft Excel file embedded in the Microsoft Word version of this document. The file can be copied and pasted into a folder and then opened as an Excel worksheet.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

LAT-TD-04085-04

Appendix B Connector Mate/Demate Log

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION: 61AT 1837

Connector(s)	Authorized by Procedure & para or NCR	Date M/D/Y	Mate or De-mate M or D	Flight or Test F or T	Verify Power Off Emp. ID#	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect	
						*Emp. ID#	QA	*Emp ID#	QA	*Emp. ID#	QA
Connector Reference Designator											
JC-0	WJ 8-10	6/10/15	D	F	WJ	WJ	WJ	WJ	WJ	WJ	WJ
JC-1											
JC-2											
JC-3											
JT-0											
JT-1											
JT-2											
JT-3											
JT-4											
JT-5											
JT-6											
JT-7											
JJ-1											

\*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Note: This Mate/Demate log is a Microsoft Excel file embedded in the Microsoft Word version of this document. The file can be copied and pasted into a folder and then opened as an Excel worksheet.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

TEM/TPS Performance Test Procedure

Appendix B Connector Mate/Demate Log

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION:

4 LAT-1837

Connector(s)	Authorized by Procedure & para or NCR	Date M/D/Y	Mate or De-mate M or D	Flight or Test F or T	Verify Power Off Emp. ID#	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect Fasteners Torqued, Witness Strips applied * Emp. ID#
						*Emp. ID#	*Emp. ID#	* Emp. ID#	* Emp. ID#	
Connector Reference Designator	WR 970	6/11/03	M	F	SAW	SAW	SAW	SAW	SAW	SAW
JC-0										
JC-1										
JC-2										
JC-3										
JT-0										
JT-1										
JT-2										
JT-3										
JT-4										
JT-5										
JT-6										
JT-7										
J-2										
JSS-1										

\*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Note: This Mate/Demate log is a Microsoft Excel file embedded in the Microsoft Word version of this document. The file can be copied and pasted into a folder and then opened as an Excel worksheet.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

LAT-TD-04085-04