

Appendix B Connector Mate/Demate Log

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION: GLAT 1838

Connector(s)	Authorized by	Date	Mate or De-mate	Flight Test or T	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID# QA	*Emp. ID# QA	*Emp. ID# QA
JTC-0	Procedure	6/9/15	M	F	SOS	SOS / 1095	SOS / 1095	SOS
JTC-1								
JTC-2								
JTC-3								
JT-0								
JT-1								
JT-2								
JT-3								
JT-4								
JT-5								
JT-6								
JT-7								
JT-8								
JT-9								
JT-10								
JT-11								
JT-12								
JT-13								

\*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Note: This Mate/Demate log is a Microsoft Excel file embedded in the Microsoft Word version of this document. The file can be copied and pasted into a folder and then opened as an Excel worksheet.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

TEM/TPS Performance Test Procedure

Appendix B Connector Mate/Demate Log

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION:

61AT 1838

Connector(s)	Authorized by	Date	Mate or De-mate	Flight or Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect
Connector Reference Designator	Procedure & para or NPR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID# QA	*Emp. ID# QA	*Emp. ID# QA
JTC-0	Bracket	4/1/15	M	F	825	825	825	825
JTC-1								
JTC-2								
JTC-3								
JTC-0								
JTC-1								
JTC-2								
JTC-3								
JTC-4								
JTC-5								
JTC-8								
JTC-9								
JTC-2								
JTC-1								

\*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Note: This Mate/Demate log is a Microsoft Excel file embedded in the Microsoft Word version of this document. The file can be copied and pasted into a folder and then opened as an Excel worksheet.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

TEM/TPS Performance Test Procedure

Appendix B Connector Mate/Demate Log

UNIT DESCRIPTION:

414T 1838 CONNECTOR MATE / DEMATE

Connector(s)	Authorized by	Date	Mate or Demate	Flight or Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID# QA	*Emp. ID# QA	Fasteners Torqued, Witness Stripe applied
STO	W0670	5/16/07	0	E	JSC	11472	11472	11472
ST1								
ST3								
ST4								
5								
6								
7								
JCO								
1								
2								
3								
JSH								

\* Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Note: This Mate/Demate log is a Microsoft Excel file embedded in the Microsoft Word version of this document. The file can be copied and pasted into a folder and then opened as an Excel worksheet.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.