

TEM/TPS Performance Test Procedure

Appendix B Connector Mate/Demate Log

UNIT DESCRIPTION: LAT 1839 **CONNECTOR MATE / DEMATE**

Connector(s)	Connector Reference Designator	Authorized by	Date	Mate or Demate	Flight or Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect
		Procedure & para or NCR <td>M/D/Y <td>M or D <td>F or T <td>Emp. ID# <td>*Emp. ID# QA</td> <td>*Emp. ID# QA</td> <td>*Emp. ID# QA</td> </td></td></td></td>	M/D/Y <td>M or D <td>F or T <td>Emp. ID# <td>*Emp. ID# QA</td> <td>*Emp. ID# QA</td> <td>*Emp. ID# QA</td> </td></td></td>	M or D <td>F or T <td>Emp. ID# <td>*Emp. ID# QA</td> <td>*Emp. ID# QA</td> <td>*Emp. ID# QA</td> </td></td>	F or T <td>Emp. ID# <td>*Emp. ID# QA</td> <td>*Emp. ID# QA</td> <td>*Emp. ID# QA</td> </td>	Emp. ID# <td>*Emp. ID# QA</td> <td>*Emp. ID# QA</td> <td>*Emp. ID# QA</td>	*Emp. ID# QA	*Emp. ID# QA	*Emp. ID# QA
	JC-0	Procedure	6/15	M	F	SN	Tom's	SN	Tom's
	JC-1								
	JC-2								
	JC-3								
	JC-0								
	JT-1								
	JT-2								
	JT-3								
	JT-4								
	JT-5								
	JT-6								
	JT-7								
	JT-8								
	JT-9								
	JT-2								

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Note: This Mate/Demate log is a Microsoft Excel file embedded in the Microsoft Word version of this document. The file can be copied and pasted into a folder and then opened as an Excel worksheet.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

TEM/TPS Performance Test Procedure

Appendix B Connector Mate/Demate Log

UNIT DESCRIPTION: 4LAT 1839 **CONNECTOR MATE / DEMATE**

Connector(s)	Authorized by	Date	Mate or Demate	Flight or Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect	
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID#	QA	*Emp. ID#	QA
3C0	UD870	6/10/85	0	F	336		1/235		1/235
3C1									
3C2									
3C3									
3TD									
3T1									
3T2									
3T3									
3T4									
3T5									
3T6									
3T7									
3T8									

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Note: This Mate/Demate log is a Microsoft Excel file embedded in the Microsoft Word version of this document. The file can be copied and pasted into a folder and then opened as an Excel worksheet.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

Appendix B Connector Mate/Demate Log

UNIT DESCRIPTION: 61AT 1839 **CONNECTOR MATE / DEMATE**

Connector(s)	Authorized by	Date	Mate or Demate	Flight or Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID# QA	*Emp. ID# QA	*Emp. ID# QA
DC-0	WDGA	6/14/15	W	F	SD	SD	SD	SD
DC-1								
DC-2								
DC-3								
DT-0								
DT-1								
DT-2								
DT-3								
DT-4								
DT-5								
DT-6								
DT-7								
DT-8								
DT-9								
DT-10								
DT-11								
DT-12								
DT-13								
DT-14								
DT-15								
DT-16								
DT-17								
DT-18								
DT-19								
DT-20								

Connector /Bracket R/D:

Note: This Mate/Demate log is a Microsoft Excel file embedded in the Microsoft Word version of this document. The file can be copied and pasted into a folder and then opened as an Excel worksheet.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.