

Tower Electronics Module Stray Voltage Test

The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

UNIT DESCRIPTION:

LAT 1763

CONNECTOR MATE / DEMATE

Connector(s)	Authorized by	Date	Mate or Demate	Flight or Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID#	*Emp ID#	*Emp. ID#
TC-0	W870	6/25	D	F	SW	SW	SW	SW
TC-1								
TC-2								
TC-3								
JT-0								
JT-1								
JT-2								
JT-3								
JT-4								
JT-5								
JT-6								
JT-7								
JS-1								

*Personnel that is Mate/Demate certified:

Connector /Bracket R/D:

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

LAT-TD-04097-03

Page 168

Tower Electronics Module Stray Voltage Test

The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

UNIT DESCRIPTION: 61A1 1763 **CONNECTOR MATE / DEMATE**

Connector(s)	Authorized by	Date	Mate or Demate	Flight or Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID# QA	*Emp. ID# QA	*Emp. ID# QA
JTC-0	W0870	5/31/15	M	F	820	820 / 1254	820 / 1252	820 DMVR
JTC-1								
JTC-2								
JTC-3								
JTC-4								
JTC-5								
JTC-6								
JTC-7								
JTC-8								
JTC-9								
JTC-10								
JTC-11								
JTC-12								
JTC-13								
JTC-14								
JTC-15								
JTC-16								
JTC-17								
JTC-18								
JTC-19								
JTC-20								

*Personnel that is Mate/Demate certified:

Connector /Bracket R/D:

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

LAT-TD-04097-03