

Appendix B Connector Mate/Demate Log

UNIT DESCRIPTION: LA1 184 **CONNECTOR MATE / DEMATE**

Connector(s)	Authorized by	Date	Mate or De-mate	Flight or Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID#	*Emp ID#	*Emp. ID#
DC-0	W0B70	6/16/5	M	F	SN	SN	SN	SN
DC-1								
DC-2								
DC-3								
DT-0								
DT-1								
DT-2								
DT-3								
DT-4								
DT-5								
DT-6								
DT-7								
DT-8								
DT-9								
DT-10								

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Note: This Mate/Demate log is a Microsoft Excel file embedded in the Microsoft Word version of this document. The file can be copied and pasted into a folder and then opened as an Excel worksheet.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

TEM/TPS Performance Test Procedure

Appendix B Connector Mate/Demate Log

UNIT DESCRIPTION:

GLAT 1821 CONNECTOR MATE / DEMATE

Connector(s)	Authorized by	Date	Mate or De-mate	Flight or Test	Verify Power Off	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect Fasteners Torqued, Witness Stripe applied
						*Emp. ID#	QA	*Emp ID#	QA	
551	20830	6/21/05	M	F	SC	SC	QA	QA	QA	QA
552										
550										
551										
552										
553										
550										
551										
552										
553										
554										
555										
556										
557										

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D: CA 4 CA 4 CA 4

Note: This Mate/Demate log is a Microsoft Excel file embedded in the Microsoft Word version of this document. The file can be copied and pasted into a folder and then opened as an Excel worksheet.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.