

TEM/TPS Performance Test Procedure

Appendix B Connector Mate/Demate Log

UNIT DESCRIPTION:

LAT 1364

CONNECTOR MATE / DEMATE

Connector(s)	Authorized by	Date	Mate or Demate	Flight or Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID# QA	*Emp ID# QA	*Emp. ID# QA
TC-0	Procedure	6/15	D	F	RD	RD	RD	RD
TC-1								
TC-2								
TC-3								
JT-0								
JT-1								
JT-2								
JT-3								
JT-4								
JT-5								
JT-6								
JT-7								
JT-1								
JS-1								

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Note: This Mate/Demate log is a Microsoft Excel file embedded in the Microsoft Word version of this document. The file can be copied and pasted into a folder and then opened as an Excel worksheet.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

TEM/TPS Performance Test Procedure

Appendix B Connector Mate/Demate Log

UNIT DESCRIPTION: LAI 1764 **CONNECTOR MATE / DEMATE**

Connector(s)	Authorized by Procedure & para or NCR	Date M/D/Y	Mate or Demate M or D	Flight or Test F or T	Verify Power Off Emp. ID#	Pre-mate Inspect *Emp. ID#	QA	ESD Bleed and Connector Mate *Emp ID#	QA	Final Inspect Fasteners Torqued, Witness Strips applied *Emp. ID#	QA
J-1		6/8/5	D	F	M.O. XW XW XW	M.O. XW XW XW	1/27	M.O. XW XW XW	1/27	M.O. XW XW XW	1/27
J-1		6/8/5	M	F	XW XW XW	XW XW XW		XW XW XW		XW XW XW	
J-1		6/8/5	D	F	XW XW XW	XW XW XW		XW XW XW		XW XW XW	

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Note: This Mate/Demate log is a Microsoft Excel file embedded in the Microsoft Word version of this document. The file can be copied and pasted into a folder and then opened as an Excel worksheet.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

TEM/TPS Performance Test Procedure

Appendix B Connector Mate/Demate Log

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION:

GLAI 1564

Connector(s)	Authorized by	Date	Mate or Demate	Flight or Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect Fasteners Torqued, Witness Stride applied
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID# QA	*Emp. ID# QA	*Emp. ID# QA
ICC0	Procedure	11/24/04	M	F	1122	1122	1122	1122
ICC1								
ICC2								
ICC3								
IT-1								
IT-2								
IT-3								
IT-4								
IT-5								
IT-6								
IT-7								
IS1								
IT-0								

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Note: This Mate/Demate log is a Microsoft Excel file embedded in the Microsoft Word version of this document. The file can be copied and pasted into a folder and then opened as an Excel worksheet.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.