

TEM/TPS Performance Test Procedure

Appendix B Connector Mate/Demate Log

UNIT DESCRIPTION: GLAT1788 (AT114) **CONNECTOR MATE / DEMATE**

Connector(s)	Authorized by	Date	Mate or Demate	Flight or Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect Fasteners Torqued, Witness Stripe applied
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID# QA	*Emp ID# QA	*Emp. ID# QA
F-1	W0872	5/26/5	M	F	SL	SL	SL	SL
F-1		5/26/5	M	F	SL	SL	SL	SL
F-1		5/26/5	M	F	SL	SL	SL	SL
F-1		5/26/5	M	F	SL	SL	SL	SL
F-1		5/27/05	D	F	SL	SL	SL	SL
F-1		5/27/05	M	F	SL	SL	SL	SL
F-1		6/8/05	D	F	SL	SL	SL	SL
F-1		6/8/05	M	F	SL	SL	SL	SL

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Note: This Mate/Demate log is a Microsoft Excel file embedded in the Microsoft Word version of this document. The file can be copied and pasted into a folder and then opened as an Excel worksheet.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.