

TPS Subassembly Electrical Interface Continuity and Isolation Test

The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

UNIT DESCRIPTION:

LAT1787 (GT117) **CONNECTOR MATE / DEMATE**

Connector(s)	Authorized by	Date	Mate or Demate	Flight or Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID#	*Emp ID#	Fasteners Torqued, Witness Stripe applied
S1	W087A	6/6/05	M	F	SC	SC	SC	SC
S2	W087A	6/6/05	M	F	SC	SC	SC	SC
S1	W087A	6/8/05	D	F	SC	SC	SC	SC
S2	W087A	6/8/05	D	F	SC	SC	SC	SC

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D: