

TEM/TPS Performance Test Procedure

Appendix B Connector Mate/Demate Log

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION: LAT 1760

Connector(s)	Authorized by	Date	Mate or Demate	Flight Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID# QA	*Emp. ID# QA	Fasteners Torqued, Witness Stripe applied
SC-0	Procedure 4/15		D	F	SD	SD	SD	SD
SC-1								
SC-2								
SC-3								
DT-0								
DT-1								
DT-2								
DT-3								
DT-4								
DT-5								
DT-6								
DT-7								
DT-1								
DT-1								

\*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Note: This Mate/Demate log is a Microsoft Excel file embedded in the Microsoft Word version of this document. The file can be copied and pasted into a folder and then opened as an Excel worksheet.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

TEM/TPS Performance Test Procedure

Appendix B Connector Mate/Demate Log

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION: LAT 1360

Connector(s)	Authorized by	Date	Mate or De-mate	Flight or Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect
Connector Reference Designator	Procedure & para or NGR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID# QA	*Emp. ID# QA	*Emp. ID# QA
JC-0	Procedure	6/15	M	F	SD	SD 1025	SD 1025	SD 1025
JC-1								
JC-2								
JC-3								
JT-0								
JT-1								
JT-2								
JT-3								
JT-4								
JT-5								
JT-6								
JT-7								
JT-1								
JS-1								

\*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Note: This Mate/Demate log is a Microsoft Excel file embedded in the Microsoft Word version of this document. The file can be copied and pasted into a folder and then opened as an Excel worksheet.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.