

UNIT DESCRIPTION: 67LAT 1841 Connector Mate/Demate Log

Connector(s)	Authorized by	Date	Mate or Demate	Flight or Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect	
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID#	QA	*Emp. ID#	QA
IC-0	WA 669	10/21/15	M	F	810	810	810	810	810
IC-1				F					
IC-2				F					
IC-3				F					
JT-0				F					
JT-1				F					
JT-2				F					
JT-3				F					
JT-4				F					
JT-5				F					
JT-6				F					
JT-7				F					
J-1				F					
JS-1				F					

*Personnel that is Mate/Demate certified:

Connector /Bracket R/D:

UNIT DESCRIPTION:

61511844

Connector Mate/Demate Log

Connector(s)	Authorized by	Date	Mate or Demate	Flight or Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID#	*Emp. ID#	Fasteners Torqued, Witness Stripe applied
IC-0	W. [Signature]	6/30/15	D	F	[Signature]	[Signature]	[Signature]	[Signature]
IC-1				F				
IC-2				F				
IC-3				F				
JT-0				F				
JT-1				F				
JT-2				F				
JT-3				F				
JT-4				F				
JT-5				F				
JT-6				F				
JT-7				F				
J-1				F				
JS-1				F				

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

UNIT DESCRIPTION:

91AT1847 Connector Mate/Demate Log

Connector(s)	Authorized by	Date	Mate or Demate	Flight or Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID#	*Emp. ID#	*Emp. ID#
IC-0	LD 1809	7/15	M	F	DN	DN	DN	DN
IC-1				F				
IC-2				F				
IC-3				F				
JT-0				F				
JT-1				F				
JT-2				F				
JT-3				F				
JT-4				F				
JT-5				F				
JT-6				F				
JT-7				F				
J-1				F				
JS-1				F				

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D: