

Connector Mate/Demate Log

UNIT DESCRIPTION:

GLAT 1845

Connector(s)	Authorized by Procedure & para or NCR	Date M/D/Y	Mate or De-mate M or D	Flight or Test F or T	Verify Power Off Emp. ID#	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect	
						*Emp. ID#	QA	*Emp. ID#	QA	*Emp. ID#	QA
Connector Reference Designator	W0669	7/6/5	D	F	SW	SW	SW	SW	SW	SW	SW
JC-0				F							
JC-1				F							
JC-2				F							
JC-3				F							
JT-0				F							
JT-1				F							
JT-2				F							
JT-3				F							
JT-4				F							
JT-5				F							
JT-6				F							
JT-7				F							
J-1				F							
JS-1				F							

*Personnel that is Mate/Demate certified.

Connector
/Bracket

R/D:

Connector Mate/Demate Log

UNIT DESCRIPTION: GLAT 1845

Connector(s)	Authorized by Procedure & para of NCR	Date M/D/Y	Mate or De-mate M or D	Flight or Test F or T	Verify Power Off Emp. ID#	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect	
						*Emp. ID#	QA	*Emp ID#	QA	*Emp. ID#	QA
Connector Reference Designator											
JC-0	120669	7/19/15	M	F	SW	SW	QA	SW	QA	SW	QA
JC-1				F							
JC-2				F							
JC-3				F							
JT-0				F							
JT-1				F							
JT-2				F							
JT-3				F							
JT-4				F							
JT-5				F							
JT-6				F							
JT-7				F							
J-1				F							
JS-1				F							

*Personnel that is Mate/Demate certified.

Connector
/Bracket

R/D: