

TEM/TPS Performance Test Procedure

Appendix B Connector Mate/Demate Log

UNIT DESCRIPTION: 41A5 F462 **CONNECTOR MATE / DEMATE**

Connector(s)	Authorized by	Date	Mate or Demate	Flight or Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID# QA	*Emp. ID# QA	*Emp. ID# QA
JC-0	10870	6/16/5 D	D	F	AW	SD 1035	SD 1035	SD 1035
JC-1								
JC-2								
JC-3								
JT-0								
JT-1								
JT-2								
JT-3								
JT-4								
JT-5								
JT-6								
JT-7								
JT-8								
JS-1								

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Note: This Mate/Demate log is a Microsoft Excel file embedded in the Microsoft Word version of this document. The file can be copied and pasted into a folder and then opened as an Excel worksheet.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

Appendix B Connector Mate/Demate Log

UNIT DESCRIPTION:

61A1 CONNECTOR MATE / DEMATE

Connector(s)	Authorized by	Date	Mate or De-mate	Flight or Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect Fasteners Torqued, Witness Stripe applied
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID#	*Emp. ID#	QA
2C-0	WDB	1/10/15	M	F	825	825	825	1/13/15
2C-1								
2C-2								
2C-3								
2C-0								
2T-1								
2T-2								
2T-3								
2T-4								
2T-5								
2T-6								
2T-7								
2T-1								
2S-1								

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Note: This Mate/Demate log is a Microsoft Excel file embedded in the Microsoft Word version of this document. The file can be copied and pasted into a folder and then opened as an Excel worksheet.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.