

TPS Subassembly Electrical Interface Continuity and Isolation Test

The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION: GLAT1792 (GT122)

Connector(s)	Authorized by	Date	Mate or De-mate	Flight or Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID# / QA	*Emp. ID# / QA	*Emp. ID# / QA
J1	WO872	6/17/2005	M	F	IL 52 6/21	IL 52 6/21	IL 52 6/21	IL 52 6/21
J2	WO872	6/17/2005	M	F	IL 52	IL 52	IL 52	IL 52
J1	WO872	6/20/2005	D	F	IL 52	IL 52	IL 52	IL 52
J2	WO872	6/20/2005	D	F	IL 52	IL 52	IL 52	IL 52

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D: