

UNIT DESCRIPTION:

QUAT 1846

Connector Mate/Demate Log

Connector(s)	Authorized by	Date	Mate or Demate	Flight or Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect
Connector Reference Designator	Procedure & para of NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID#	*Emp. ID#	*Emp. ID#
JC-0	W01009	7/18/15	M	F	820	820	1205	820/1205
JC-1								
JC-2								
JC-3								
JT-0								
JT-1								
JT-2								
JT-3								
JT-4								
JT-5								
JT-6								
JT-7								
J-1								
JS-1								

*Personnel that is Mate/Demate certified:

Connector /Bracket R/D:

UNIT DESCRIPTION:

61AT 1846

Connector Mate/Demate Log

Connector(s) Connector Reference Designator	Authorized by Procedure & para or NOR	Date M/D/Y	Mate or De-mate M or D	Flight or Test F or T	Verify Power Off Emp. ID#	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect Fasteners Torqued, Witness Stripe applied	
						*Emp. ID#	QA	*Emp. ID#	QA	*Emp. ID#	QA
IC-0	WOUH	7/11/15	D	F	SP	SP	SP	SP	SP	SP	SP
IC-1											
IC-2											
IC-3											
JT-0											
JT-1											
JT-2											
JT-3											
JT-4											
JT-5											
JT-6											
JT-7											
J-1											
JS-1											

*Personnel that is Mate/Demate certified.

Connector
/Bracket

R/D:

UNIT DESCRIPTION: 6441 1846 Connector Mate/Demate Log

Connector(s)	Authorized by	Date	Mate or Demate	Flight or Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID#	*Emp. ID#	*Emp. ID#
JC-0	NOA69	7/8/5	M	F	800	800	800	800
JC-1				F				
JC-2				F				
JC-3				F				
JT-0				F				
JT-1				F				
JT-2				F				
JT-3				F				
JT-4				F				
JT-5				F				
JT-6				F				
JT-7				F				
J-1				F				
JS-1				F				

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D: