

Connector Mate/Demate Log

UNIT DESCRIPTION: GLAT 1847

Connector(s)	Authorized by Procedure & para or NCB	Date M/D/Y	Mate or De-mate M or D	Flight or Test F or T	Verify Power Off Emp. ID#	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Fast Witness *Emp. ID#
						*Emp. ID#	QA	*Emp. ID#	QA	
Connector Reference Designator	William	7/6/15	M	F	820	820	Y/C	820	Y/C	820
JC-0										
JC-1										
JC-2										
JC-3										
JT-0										
JT-1										
JT-2										
JT-3										
JT-4										
JT-5										
JT-6										
JT-7										
J-1										
JS-1										

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Connector Mate/Demate Log

UNIT DESCRIPTION: GLAT 1847

Connector(s)	Authorized by Procedure & para or NCR	Date M/D/Y	Mate or De-mate M or D	Flight or Test F or T	Verify Power Off Emp. ID#	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect	
						*Emp. ID#	QA	*Emp ID#	QA	* Emp. ID#	QA
Connector Reference Designator											
IC-0	W. Kelly	7/26/15	D	F	JK		YL		YL		YL
IC-1											
IC-2											
IC-3											
JT-0											
JT-1											
JT-2											
JT-3											
JT-4											
JT-5											
JT-6											
JT-7											
J-1											
JS-1											

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Connector Mate/Demate Log

UNIT DESCRIPTION:

GAT 1847

Connector(s)	Authorized by Procedure & para or NCR	Date M/D/Y	Mate or De-mate M or D	Flight or Test F or T	Verify Power Off Emp. ID#	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect	
						*Emp. ID#	QA	*Emp. ID#	QA	*Emp. ID#	QA
IC-0	W0667	7/25/5	M	F	JW	JW	JW	JW	JW	JW	JW
IC-1											
IC-2											
IC-3											
JT-0											
JT-1											
JT-2											
JT-3											
JT-4											
JT-5											
JT-6											
JT-7											
J-1											
JS-1											

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D: