

UNIT DESCRIPTION:

41A1 Hole Connector Mate/Demate Log

Connector(s)	Authorized by	Date	Mate or Demate	Flight or Test	Verify Power Off	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect	
						*Emp. ID#	CA	*Emp. ID#	CA	*Emp. ID#	CA
IC-0	W.D. B. D.	7/14/15	D	F	D	D	W.D. B. D.	W.D. B. D.	D	D	
IC-1											
IC-2											
IC-3											
JT-0											
JT-1											
JT-2											
JT-3											
JT-4											
JT-5											
JT-6											
JT-7											
J-1											
JS-1											

\*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

UNIT DESCRIPTION:

41A1 BACE

Connector Mate/Demate Log

Connector(s)	Authorized by	Date	Mate or Demate	Flight or Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect
Connector Reference Designator	Procedure & para or NCS	MM/DD/YY	M or D	F or T	Emp. ID#	*Emp. ID#	*Emp. ID#	Fasteners Torqued, Witness Strips applied
IC-0	ADSD	7/5/15	M	F	DA	DA	DA	DA
IC-1								
IC-2								
IC-3								
JT-0								
JT-1								
JT-2								
JT-3								
JT-4								
JT-5								
JT-6								
JT-7								
J-1								
JS-1								

\*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

TEM/TFS Performance Test Procedure

Appendix B Connector Mate/Demate Log

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION: 614T Hole

Connector(s)	Authorized by	Date	Mate or Demate	Flight or Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp ID#	*Emp ID#	*Emp ID#	Fasteners Torqued, Witness, Specs checked
JC-0	Procedure 617/5	7/15	M	F	RD	RD	RD	RD
JC-1								
JC-2								
JC-3								
JT-0								
JT-1								
JT-2								
JT-3								
JT-4								
JT-5								
JT-6								
JT-7								
JT-8								
JT-9								
JT-10								
JT-11								
JT-12								
JT-13								
JT-14								
JT-15								
JT-16								
JT-17								
JT-18								
JT-19								
JT-20								
JT-21								
JT-22								
JT-23								
JT-24								
JT-25								
JT-26								
JT-27								
JT-28								
JT-29								
JT-30								
JT-31								
JT-32								
JT-33								
JT-34								
JT-35								
JT-36								
JT-37								
JT-38								
JT-39								
JT-40								
JT-41								
JT-42								
JT-43								
JT-44								
JT-45								
JT-46								
JT-47								
JT-48								
JT-49								
JT-50								
JT-51								
JT-52								
JT-53								
JT-54								
JT-55								
JT-56								
JT-57								
JT-58								
JT-59								
JT-60								
JT-61								
JT-62								
JT-63								
JT-64								
JT-65								
JT-66								
JT-67								
JT-68								
JT-69								
JT-70								
JT-71								
JT-72								
JT-73								
JT-74								
JT-75								
JT-76								
JT-77								
JT-78								
JT-79								
JT-80								
JT-81								
JT-82								
JT-83								
JT-84								
JT-85								
JT-86								
JT-87								
JT-88								
JT-89								
JT-90								
JT-91								
JT-92								
JT-93								
JT-94								
JT-95								
JT-96								
JT-97								
JT-98								
JT-99								
JT-100								

\*Personnel that is Mate/Demate certified  
 J-1

Connector /Bracket R/D:

Note: This Mate/Demate log is a Microsoft Excel file embedded in the Microsoft Word version of this document. The file can be copied and pasted into a folder and then opened as an Excel worksheet.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.