

UNIT DESCRIPTION: GLAT 1849 Connector Mate/Demate Log

Connector(s)	Authorized by	Date	Mate or Demate	Flight or Test	Verify Power Off	Pro-mate Inspect	ESD Bleed and Connector Mate	Final Inspect
Connector Reference Designator	Procedure & para or NCR	MOY	M or D	F or T	Emp. ID#	Emp. ID# QA	Emp. ID# QA	Emp. ID# QA
IC-0	WPK	7/27/15	M	F	SD	SD 71020	SD 71020	SD 71020
IC-1								
IC-2								
IC-3								
JT-0								
JT-1								
JT-2								
JT-3								
JT-4								
JT-5								
JT-6								
JT-7								
J-1								
JS-1								

* Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

UNIT DESCRIPTION:

4LAT 1849

Connector Mate/Demate Log

Connector(s)	Authorized by	Date	Mate or Demate	Flight or Test	Verify power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect	
Connector Reference Designator	Procedure & para or NCR	MM/DD/YY	M or D	F or T	Emp ID#	*Emp ID#	QA	*Emp ID#	QA
IC-0	W0669	9/2/5	D	F	80		QA		QA
IC-1									
IC-2									
IC-3									
JT-0									
JT-1									
JT-2									
JT-3									
JT-4									
JT-5									
JT-6									
JT-7									
J-1									
JS-1									

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

UNIT DESCRIPTION: 61AT 1849 Connector Mate/Demate Log

Connector(s)	Authorized by	Date	Mate or Demate	Flight or Test	Verify Power On	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect
Connector Reference Designator	Procedure & para or NCR	MMYY	M or D	F or T	Emp ID#	*Emp ID# QA	*Emp ID# QA	*Emp ID# QA
IC-0	W.D. GAG	8/3/5	M	F	SA	SA	SA	SA
IC-1								
IC-2								
IC-3								
JT-0								
JT-1								
JT-2								
JT-3								
JT-4								
JT-5								
JT-6								
JT-7								
J-1								
JS-1								

* Personnel that is Mate/Demate certified

Connector /Bracket R/D: