

TKR top tray was used instead of real TKR bottom tray and height of bottom tray is also different from nominal, both effects combined led to a difference in cable length of 0.16 mm and most likely is not our source of problem. Problem could be coming from Grid height, but we do not know for sure

