




APPROVED MAY 05 2004

|   |                     |  |
|---|---------------------|--|
| <br><b>GLAST Mission</b><br><b>Interface Change Notice (ICN)</b>                             |                     | ICN No.<br>057   |
|   |                     | SHEET <u>1</u> OF 3  |
| ORIGINATOR: Rich Bielawski  | PHONE: 650-926-5190 | DATE: 4-22-04  |
| CHANGE TITLE: LAT 1553 Connector Part Number  |                     | ORG: LAT   |
| DOCUMENT NUMBER   | TITLE               | VERSION  |
| 1196-EI-Y46311-000  | LAT-SC ICD          | B  |
| <b>REASON FOR CHANGE:</b><br>To reduce the risk of damage to the LAT EMI shield mounted 1553 connectors during LAT I&T, part number BJ3154-47 will be used instead of BJ3150. |                     |  |
| <b>PROPOSED CHANGE:</b><br>See attached.  |                     |  |
| <b>INSTRUMENT IMPACT</b><br><input type="checkbox"/> Cost<br><input type="checkbox"/> Schedule  | None.               |  |
| <b>SPACECRAFT IMPACT</b><br><input type="checkbox"/> Cost<br><input type="checkbox"/> Schedule  |                     |  |
| ORIGINATOR SIGNATURE:   |                     |  |
| APPROVAL SIGNATURES:  |                     |  |
| Spectrum Instrument Interface Lead – Tim Morse  |                     | Spectrum Program Manager – Al Lepore   |
| <br>Instrument Systems Engineer – Dick Horn  |                     | <br>Instrument Program Manager – Lowell Klaisner |